





report date: 2024-03-28

### General information

Make	FORD
Model	GALAXY TITANIUM
Colour	Silver
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	200 BHP
Max. torque	300 Nm at 4.000 rpm
Engine capacity	1.976 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 1

Date	2021-09-07
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## MOT history

MOT expiry date	2023-08-04
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	24
Total items failed	8

MOT #13	2022-08-03 13:19
MOT test number	750600173700
Result	<b>✓</b> Passed
Next expiry date	2023-08-04

MOT #12	2022-08-02 11:29	
MOT test number	549949567554	
Result	<b>X</b> Failed	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
<b>Fail</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
<b>Fail</b> Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))		

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #11** 2021-08-02 08:57 **MOT** test number 409715656807 ✓ Passed Result **Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10

MOT test number

Result

Advice Rear exhaust hangers corroded

2020-08-05 12:08

773514523838

✓ Passed

MOT test number

Result

Fail Offside Rear Suspension arm pin or bush excessively worn Trailing Arm Bushes (5.3.4 (a) (i))

Advice Rear exhaust hangers corroded

Fail Nearside Rear Suspension arm pin or bush excessively worn Trailing Arm Bushes (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #8

MOT test number

Result

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT test number

Result

Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Fail

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6

MOT test number

644286135434

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Cv boot

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #5		2017-07-01 09:20
MOT test	number	602346523373
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2016-07-13 12:18
MOT test number	693894565784
Result	✓ Passed
MOT #3	2015-06-24 11:46
MOT test number	649215475148
Result	✓ Passed
MOT #2	2014-06-18 17:32
MOT test number	405739264158
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2013-06-20 11:06
MOT test number	575711673178
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
************	
*********	
***********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-21
Last registration	2022-08-03
Complete history	See info



Registration #1	2010-06-21	6 mi
Registration #2	2013-06-20	53.627 mi
Registration #3	2014-06-18	58.054 mi
Registration #4	2015-06-24	63.195 mi
Registration #5	2016-07-13	69.124 mi
Registration #6	2017-07-01	75.264 mi
Registration #7	2018-08-03	87.277 mi
Registration #8	2019-08-04	94.840 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

50225	Air conditionin
50295	
60482	
50501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1697 kg
Max. allowed weight	2450 kg

## Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

Engine number AP42778