



report date: 2024-03-28

General information

Make	MAZDA
Model	5 D SPORT NAV 4WD
Colour	White
Year of manufacture	2012
Top speed	129 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 2

Date	2022-08-10
Pictures	30
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-12-08
Pictures	30
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2023-05-04
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #10	2022-05-04 07:42
MOT test number	860748865899
Result	✓ Passed
Next expiry date	2023-05-04
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9	2021-05-01 06:24
MOT test number	839636037894
Result	✓ Passed

MOT #8	2020-04-27 12:06
MOT test number	879698946147
Result	✓ Passed

MOT #7	2019-04-30 08:39
MOT test number	517109405451
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2018-05-01 15:32**MOT test number** 507726458642**Result** ✓ Passed**MOT #5** 2018-05-01 11:37**MOT test number** 604419665885**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre 225/55/19/99v toyo 4x4**Fail** Offside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)**Advice** Nearside Front Nail in tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-05-04 13:58**MOT test number** 304093180233**Result** ✓ Passed**MOT #3** 2017-05-03 16:31**MOT test number** 635761173643**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2016-05-05 08:45**MOT test number** 680924222526**Result** ✓ Passed



MOT #1	2015-04-16 13:08
MOT test number	835626605108
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✕
Untaxed

Tax expired:
17 October 2022

✕
MOT

Expired:
4 May 2023

Tax status	Expired at 17 October 2022
Days left	560 days too late
MOT expiry date	4 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-28
Current registration	XXXX XX
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-04-30
Last registration	2022-05-04
Complete history	See info



Registration #1	2012-04-30	23 mi
Registration #2	2015-04-16	64.267 mi
Registration #3	2016-05-05	74.966 mi
Registration #4	2017-05-03	86.701 mi
Registration #5	2017-05-04	86.701 mi
Registration #6	2018-05-01	95.272 mi
Registration #7	2018-05-01	95.272 mi
Registration #8	2019-05-01	95.272 mi
Registration #9	2019-05-01	95.272 mi
Registration #10	2019-05-01	95.272 mi
Registration #11	2019-05-01	95.272 mi
Registration #12	2019-05-01	95.272 mi
Registration #13	2022-05-04	95.272 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	87%
Pedestrian	64%
Safety systems	86%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1670 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1530 kg
Max. allowed weight	2105 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30201323