



TOYOTA

HI2PLR

report date: 2024-03-28

General information

Make	TOYOTA
Model	PREVIA VVTI GS 8 STR
Colour	Silver
Year of manufacture	2000
Top speed	108 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	225 Nm at 4.000 rpm
Engine capacity	2.362 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.0 mpg
Consumption extra urban	33.2 mpg
Consumption combined	26.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-10
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-01
MOT pass rate	79 %
MOT passed	19
Failed MOT tests	5
Total advice items	36
Total items failed	10

MOT #24	2024-04-02 16:27
MOT test number	177281759632
Result	✓ Passed
Next expiry date	2025-04-01

MOT #23	2024-04-02 07:52
MOT test number	406362700914
Result	✗ Failed
Advice	Tyre worn close to legal limit/worn on edge O/S/F and O/S/R advise replace (5.2.3 (e))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #22	2023-03-29 07:25
MOT test number	267720124377
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #21** 2023-03-23 17:27**MOT test number** 768683091462**Result** ✗ Failed

- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #20 2022-03-31 09:16**MOT test number** 630439675193**Result** ✓ Passed**MOT #19** 2022-03-30 14:57**MOT test number** 974693996958**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

**MOT #18**

2021-05-28 11:49

MOT test number

518374241210

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both nearside and offside (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Coil spring corroded Both nearside and offside (5.3.1 (b) (i))

Advice Nearside Front Tyre worn on edges

MOT #17

2021-05-25 13:33

MOT test number

596339682193

Result

✗ Failed

Advice Rear Coil spring corroded Both nearside and offside (5.3.1 (b) (i))

Advice Nearside Front Tyre worn on edges

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Hole to outer sill (5.3.6 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both nearside and offside (1.1.14 (a) (ii))

MOT #16

2020-06-15 10:33

MOT test number

911738906598

Result

✓ Passed

**MOT #15** 2019-06-10 15:56**MOT test number** 430464786864**Result** ✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2018-06-12 11:21**MOT test number** 342757700012**Result** ✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt rear
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13 2017-06-26 11:39**MOT test number** 893887686928**Result** ✓ Passed**MOT #12** 2016-07-04 09:03**MOT test number** 884114897439**Result** ✓ Passed

**MOT #11** 2015-06-16 16:31**MOT test number** 306317465122**Result** ✓ Passed**MOT #10** 2014-07-01 13:36**MOT test number** 889562184164**Result** ✓ Passed**MOT #9** 2013-06-21 09:21**MOT test number** 255702973468**Result** ✓ Passed**MOT #8** 2012-06-21 14:16**MOT test number** 939393872108**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-06-29 15:03**MOT test number** 888170481135**Result** ✓ Passed**MOT #6** 2010-07-12 11:09**MOT test number** 464503490184**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-07-12 11:09**MOT test number** 861463890133**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2009-07-10 11:41**MOT test number** 602851999173**Result** ✓ Passed**MOT #3** 2008-07-16 09:12**MOT test number** 184648998157**Result** ✓ Passed**MOT #2** 2007-07-03 12:33**MOT test number** 373144987109**Result** ✓ Passed**MOT #1** 2006-07-11 11:54**MOT test number** 922242596133**Result** ✓ Passed**Notice** Front pads low.**Notice** Rear seatbelts not checked,seats not fitted.



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
1 April 2025

Tax status

Valid until 1 April

Days left

338

MOT expiry date

1 April 2025

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2000-07-20
Last registration	2024-04-02
Complete history	See info



Registration #1	2000-07-20	18 mi
Registration #2	2006-07-11	28.094 mi
Registration #3	2007-07-03	31.624 mi
Registration #4	2008-07-16	36.961 mi
Registration #5	2009-07-10	41.796 mi
Registration #6	2010-07-12	45.590 mi
Registration #7	2011-06-29	50.290 mi
Registration #8	2012-06-21	52.913 mi
Registration #9	2013-06-21	54.852 mi
Registration #10	2014-07-01	55.941 mi
Registration #11	2015-06-16	56.556 mi
Registration #12	2016-07-04	57.333 mi
Registration #13	2017-06-26	59.160 mi
Registration #14	2018-06-26	61.000 mi
Registration #15	2019-06-26	62.850 mi
Registration #16	2020-06-26	64.700 mi
Registration #17	2021-06-26	66.550 mi
Registration #18	2022-06-26	68.400 mi
Registration #19	2023-06-26	70.250 mi
Registration #20	2024-03-28	72.100 mi
Registration #21	2024-03-28	74.000 mi
Registration #22	2024-03-28	75.900 mi
Registration #23	2024-03-28	77.800 mi
Registration #24	2024-03-28	79.700 mi
Registration #25	2024-03-28	81.600 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1790 mm
Height	1770 mm
Length	4750 mm
Wheel base	2900 mm
Kerb weight	1600 kg

Additional information

Fuel tank capacity	76 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2AZ0085050