





report date: 2024-01-16

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V HIGHLINE BMT
Colour	Grey
Year of manufacture	2016
Top speed	98 mph
0 - 100 km/h	15.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-01-16

Internet history

Entry 4

Date 2022-02-08

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

Date	2022-01-05
Pictures	0

Listing price <u>View report</u>

source: heycar.co.uk

Entry 2

Date	2021-09-21

Pictures 40

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-21
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



GK16VHG
report date: 2024-01-16

MOT history

MOT expiry date	2025-02-17
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	6

MOT #8	2024-02-08 10:11
MOT test number	677012824212
Result	✓ Passed
Next expiry date	2025-02-17
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2023-02-15 12:54
MOT test	number	721166884005
Result		✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (235/50R1	Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn low on our 8). (5.2.3 (e))	ter edge
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-01-16

MOT #6 2023-02-15 10:18 **MOT** test number 273726528361 Result × Failed **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Fail Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Fail Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn low on outer edge (235/50R18). (5.2.3 (e)) Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #5	2022-02-18 12:35
MOT test number	933997742591
Result	✓ Passed
MOT #4	2022-02-17 14:37
MOT test number	809724801830
Result	× Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))	

MOT #3	2021-07-05 07:39
MOT test number	501321665375
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-01-16

MOT #2 2020-03-18 10:48

MOT test number 840258877841

Result ✓ Passed

Minor Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2019-03-05 12:59

MOT test number 668734365736

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

(i))

CarCheck.co.uk page 5/12



report date: 2024-01-16

Tax & MOT check





Tax status	Valid until 1 February
Days left	328
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-01-16

Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Date
Category



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-01-16

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-01-16

More info >

Owner history

·		_
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many vOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.		

	More info >	
Plate changes		
See in this check if this VOLKSWAGEN had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	NK SIN	
Plate since		

CarCheck.co.uk page 9/12



report date: 2024-01-16

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-01-16

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-03-11
Last registration	2024-02-08
Complete history	See info



Registration #1	2016-03-11	24 mi
Registration #2	2019-03-05	32.699 mi
Registration #3	2020-03-18	44.035 mi
Registration #4	2021-07-05	52.066 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-01-16

Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1990 mm
Length	4892 mm
Wheel base	3400 mm
Kerb weight	1916 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of seats	3
CarChack co.uk	nago 12/11

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	CAAB919830