



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	LAGUNA DYNAMIQUE DCI (150BHP)
Colour	Grey
Year of manufacture	2007
Top speed	132 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 2


Date	2023-04-30
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-10-03
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-02-01
MOT pass rate	52 %
MOT passed	12
Failed MOT tests	11
Total advice items	76
Total items failed	16

MOT #23 2023-02-23 16:58

MOT test number 954771445468

Result ✗ Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Rear window missing but not effecting view to rear

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Nearside Rear Hydraulic brake calliper leaking and braking performance affected (1.1.16 (b) (ii))

MAJOR Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Fuel tank bracket broken fuel tank secure

MAJOR Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

**MOT #22**

2023-02-23 09:32

MOT test number

105873980692

Result**✗ Failed**

- MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Front Position lamp not working both front position lights (4.2.1 (a) (ii))
- Advice** Headlamp has a product on the lens but not seriously reducing light output both front headlights cloudy (4.1.4 (b))
- DANGEROUS** Nearside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear window missing but not effecting view to rear
- Advice** Fuel tank bracket broken fuel tank secure
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

MOT #21

2022-02-02 14:20

MOT test number

723802718576

Result**✓ Passed**

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #20** 2021-01-29 16:58**MOT test number** 507083884719**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Shock slightly corroded**Advice** Front Undertray not fully secure (8.1.1 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #19** 2021-01-29 10:16**MOT test number** 507262374501**Result** ✗ Failed**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Number plate dirty**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Undertray not fully secure (8.1.1 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Shock slightly corroded**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Items removed from driver's view prior to test**MOT #18** 2019-07-30 16:04**MOT test number** 619275128782**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #17	2018-09-01 12:08
MOT test number	168982012166
Result	✓ Passed

MOT #16	2018-08-17 11:51
MOT test number	955533325255
Result	✗ Failed
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #15**

2018-06-27 10:57

MOT test number

140581517516

Result

✗ Failed

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material going to nsr calliper (1.1.11 (c))**Advice** Axle swivel pins and bushes swivel pin and/or bush slightly worn both rear bushes starting to slightly split from bonding (5.1.2 (b) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Nail in tyre**Advice** Under trays fitted obscuring some components**Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MAJOR** Offside Rear Brake pipe excessively corroded going across axle in to osr calliper (1.1.11 (c))**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Both rear shock absorbers corroded**MOT #14**

2017-06-29 16:17

MOT test number

314234340484

Result

✓ Passed

Advice Play in steering rack inner joint(s)**Advice** Offside Rear Brake pipe slightly corroded going across axle to osr flexi pipe (3.6.B.2c)**Advice** Under trays fitted obscuring some components

**MOT #13** 2017-06-29 08:53**MOT test number** 455682433071**Result** ✗ Failed**Fail** Nearside Rear Direction indicators incorrect colour white light (1.4.A.2f)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Under trays fitted obscuring some components**Advice** Play in steering rack inner joint(s)**Advice** Offside Rear Brake pipe slightly corroded going across axle to osr flexi pipe (3.6.B.2c)**MOT #12** 2016-07-19 13:56**MOT test number** 890217924541**Result** ✓ Passed**Advice** Sub-frame rubber bush deteriorated but not resulting in excessive movement both rear axle bushes (2.4.G.2)**MOT #11** 2016-07-18 11:06**MOT test number** 518131161896**Result** ✗ Failed**Fail** Offside Rear brake caliper leaking (3.6.A.1)**Fail** Headlamp aim too low both (1.8)**Fail** Brake pipe excessively corroded both front to rear at rear (3.6.B.2c)**Advice** Sub-frame rubber bush deteriorated but not resulting in excessive movement both rear axle bushes (2.4.G.2)**MOT #10** 2015-07-14 14:44**MOT test number** 119455195187**Result** ✓ Passed

**MOT #9** 2015-07-14 09:59**MOT test number** 317925295179**Result** ✗ Failed**Fail** Brake pipe inadequately clipped (3.6.B.1)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #8** 2014-06-30 09:50**MOT test number** 499171884133**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #7** 2013-07-08 15:22**MOT test number** 777299083101**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #6** 2013-07-08 11:39**MOT test number** 476409783163**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #5** 2012-07-09 16:42**MOT test number** 776201092107**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-07-09 09:25**MOT test number** 697961192101**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #3** 2011-07-08 16:31**MOT test number** 866239681122**Result** ✓ Passed



MOT #2	2011-07-08 10:42
MOT test number	815279381101
Result	✗ Failed
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Fail	Rear Bonded suspension unit deteriorated and cannot function as intended (2.4.F.3)

MOT #1	2010-07-12 12:34
MOT test number	272643790453
Result	✓ Passed
Advice	Rear Bonded suspension unit deteriorated but can function as intended (2.4.F.3)



Tax & MOT check

✕
Untaxed

Tax expired:
1 February 2023

✕
MOT

Expired:
1 February 2023

Tax status	Expired at 1 February 2023
Days left	454 days too late
MOT expiry date	1 February 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	TK07ATV
Plate since	2019-03-29
Current registration	TK07ATV
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	FINANCE
Date of agreement	2024-03-29	2024-03-29
Agreement type	RENAULT	FINANCE
Agreement term	RENAULT	FINANCE
Agreement number	RENAULT	FINANCE
Contact info	RENAULT	FINANCE

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-07-26
Last registration	2023-02-23
Complete history	See info



Registration #1	2007-07-26	22 mi
Registration #2	2010-07-12	15.529 mi
Registration #3	2011-07-08	20.457 mi
Registration #4	2011-07-08	20.457 mi
Registration #5	2012-07-09	25.253 mi
Registration #6	2012-07-09	25.253 mi
Registration #7	2013-07-08	28.933 mi
Registration #8	2013-07-08	28.933 mi
Registration #9	2014-06-30	32.934 mi
Registration #10	2015-07-14	37.000 mi
Registration #11	2015-07-14	37.001 mi
Registration #12	2016-07-18	40.755 mi
Registration #13	2016-07-19	40.757 mi
Registration #14	2016-07-19	40.757 mi
Registration #15	2016-07-19	40.757 mi
Registration #16	2016-07-19	40.757 mi
Registration #17	2016-07-19	40.757 mi
Registration #18	2016-07-19	40.757 mi
Registration #19	2016-07-19	40.757 mi
Registration #20	2016-07-19	40.757 mi
Registration #21	2016-07-19	40.757 mi
Registration #22	2016-07-19	40.757 mi
Registration #23	2016-07-19	40.757 mi
Registration #24	2016-07-19	40.757 mi
Registration #25	2016-07-19	40.757 mi
Registration #26	2016-07-19	40.757 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1475 mm
Length	4713 mm
Wheel base	2748 mm
Kerb weight	1455 kg
Max. allowed weight	2085 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	C032453