



RX5IGRZ

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 16V
Colour	Green
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	148 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg





Internet history

Entry 1

Date	2021-08-10
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #22	2021-11-16 15:28
MOT test number	967535757727
Result	✓ Passed
Next expiry date	2022-11-15
Minor	Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #21	2021-11-11 09:22
MOT test number	648752525820
Result	✗ Failed
Fail	Offside Front Lower Anti-roll bar linkage fractured (5.3.3 (b) (ii))
Fail	Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))
Fail	Offside Front Inner Suspension component pin or bush excessively worn rear most (5.3.4 (a) (i))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Fail	Nearside Front Headlamp levelling device inoperative (4.1.5 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge both edges, (5.2.3 (e))
Fail	Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))
Minor	Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Front Headlamp aim too low (4.1.2 (a))

MOT #20	2020-10-26 13:19
MOT test number	618709766655
Result	✓ Passed

**MOT #19** 2020-10-26 09:54**MOT test number** 503290241563**Result** ✗ Failed**Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**MOT #18** 2019-11-12 15:01**MOT test number** 621512921414**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #17** 2019-11-12 14:31**MOT test number** 825123498372**Result** ✗ Failed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**MOT #16** 2018-11-15 12:52**MOT test number** 823749596502**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #15	2017-11-09 13:45
MOT test number	428885159536
Result	✓ Passed
Advice	Eml on.

MOT #14	2016-10-27 11:09
MOT test number	785382990627
Result	✓ Passed
Advice	Wiper blades in poor condition
Advice	Both rear coil springs corroded
Advice	Front brake pads and discs wearing low

MOT #13	2015-10-29 15:13
MOT test number	824234439184
Result	✓ Passed

MOT #12	2015-10-29 09:44
MOT test number	352573975699
Result	✗ Failed
Fail	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Advice	Nearside Rear Tyre worn close to the legal limit On limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin Inner pads are low (3.5.1g)
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Advice	Offside Rear Tyre worn close to the legal limit On limit (4.1.E.1)

MOT #11	2014-10-24 16:25
MOT test number	439047494240
Result	✓ Passed

**MOT #10** 2013-10-16 15:42**MOT test number** 169349683283**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2012-11-01 12:14**MOT test number** 635046302382**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nail in nearside front tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2012-11-01 12:14**MOT test number** 848916602390**Result** ✗ Failed**Notice** Nail in nearside front tyre**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-11-02 10:33**MOT test number** 457236701371**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #6** 2010-10-26 11:25**MOT test number** 362949590492**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2009-10-29 11:28**MOT test number** 890232409351**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #4** 2009-10-29 11:28**MOT test number** 240842309307**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2008-11-03 12:12**MOT test number** 292608908389**Result** ✓ Passed**MOT #2** 2007-11-13 13:48**MOT test number** 782947817359**Result** ✓ Passed**MOT #1** 2006-11-09 10:59**MOT test number** 834353616326**Result** ✓ Passed**Advice** Nearside front brake juddering slightly (3.7.A.2b)**Advice** Offside front brake juddering slightly (3.7.A.2b)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	RX51GRZ
Plate since	2019-06-29
Current registration	RX51GRZ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2001-11-23
Last registration	2021-11-16
Complete history	See info



Registration #1	2001-11-23	9 mi
Registration #2	2006-11-09	41.661 mi
Registration #3	2007-11-13	51.183 mi
Registration #4	2008-11-03	60.119 mi
Registration #5	2009-10-29	70.368 mi
Registration #6	2010-10-26	79.609 mi
Registration #7	2011-11-02	87.170 mi
Registration #8	2012-11-01	94.645 mi
Registration #9	2013-10-16	101.977 mi
Registration #10	2014-10-24	110.286 mi
Registration #11	2015-10-29	118.241 mi
Registration #12	2016-10-29	126.202 mi
Registration #13	2017-10-29	134.163 mi
Registration #14	2018-10-29	142.124 mi
Registration #15	2019-10-29	150.085 mi
Registration #16	2020-10-29	158.046 mi
Registration #17	2021-10-29	166.007 mi
Registration #18	2022-10-29	173.968 mi
Registration #19	2023-10-29	181.929 mi
Registration #20	2024-10-29	189.890 mi
Registration #21	2025-10-29	197.851 mi
Registration #22	2026-10-29	205.812 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1668 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

Engine number

AYD015471