



Mercedes-Benz

WM68SXB

report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | MERCEDES-BENZ |
| Model | VITO 119 BLUETEC SPORT |
| Colour | Grey |
| Year of manufacture | 2019 |
| Top speed | 128 mph |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 140 kW / 191 HP / 190 BHP |
| Max. torque | 440 Nm at 2.400 rpm |
| Engine capacity | 2.143 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 39.8 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 169 g/km |
| CO2 label | H |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2024-02-05 |
| Pictures | 0 |
| Listing price | View report |

source: [carcraft.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-13 |
| Pictures | 9 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-19 |
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #5 | 2024-02-20 13:07 |
| MOT test number | 902836347084 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-19 |

| | |
|-----------------|--|
| MOT #4 | 2023-04-17 08:42 |
| MOT test number | 423771307398 |
| Result | ✓ Passed |
| Advice | Front Registration plate deteriorated but not likely to be misread number plate cracked (0.1 (b)) |
| Minor | Front Windscreen damaged but not adversely affecting driver's view stone chips in swept area (3.2 (a) (i)) |

| | |
|-----------------|--|
| MOT #3 | 2023-04-14 13:51 |
| MOT test number | 976718159186 |
| Result | ✗ Failed |
| Advice | Front Registration plate deteriorated but not likely to be misread number plate cracked (0.1 (b)) |
| Minor | Front Windscreen damaged but not adversely affecting driver's view stone chips in swept area (3.2 (a) (i)) |
| Fail | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #2 | 2022-03-25 12:59 |
| MOT test number | 642620049148 |
| Result | ✓ Passed |



MOT #1 2022-03-22 12:47

MOT test number 509889081976

Result ✗ Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
19 February 2025

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 February |
| Days left | | 279 |
| MOT expiry date | | 19 February 2025 |
| Full MOT history | | See MOT history |

Tax calculation

| | |
|---------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  WM68SXB |
| Plate since | 2019-06-29 |
| Current registration |  WM68SXB |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2019-01-31 |
| Last registration | 2024-02-20 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-01-31 | 9 mi |
| Registration #2 | 2020-03-22 | 75.423 mi |
| Registration #3 | 2022-03-22 | 75.423 mi |
| Registration #4 | 2022-03-25 | 75.428 mi |
| Registration #5 | 2024-02-20 | 75.428 mi |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2244 mm |
| Height | 1910 mm |
| Length | 4895 mm |
| Wheel base | 3 mm |
| Kerb weight | 1935 kg |
| Max. allowed weight | 3200 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 57 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|-----------------|----------------|
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 65195034757936 |