



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	2009
Top speed	125 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 3

Date	2022-01-20
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-12-30
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-12-07
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-05
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	31
Total items failed	6

MOT #21	2024-04-06 13:47
MOT test number	667881937315
Result	✓ Passed
Next expiry date	2025-04-05
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20	2024-03-28 18:28
MOT test number	265462333921
Result	✗ Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Offside Front Upper Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2023-04-06 17:30
MOT test number	760345684944
Result	✓ Passed

**MOT #18** 2022-04-02 13:14**MOT test number** 252711727961**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17** 2022-03-12 11:39**MOT test number** 682349419253**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Headlamp levelling device inoperative (4.1.5 (a))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #16** 2021-02-26 13:09**MOT test number** 498594440935**Result** ✓ Passed**MOT #15** 2020-03-14 10:36**MOT test number** 462532181602**Result** ✓ Passed

**MOT #14** 2020-03-13 17:57**MOT test number** 867664344365**Result** ✗ Failed**MAJOR** Offside Rear Headlamp not working on main beam (4.1.1 (a) (ii))**MAJOR** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**MOT #13** 2019-04-10 13:43**MOT test number** 883335495581**Result** ✓ Passed**MOT #12** 2019-04-06 10:38**MOT test number** 360978153411**Result** ✗ Failed**MAJOR** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**MAJOR** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**MOT #11** 2018-04-18 13:38**MOT test number** 759340026549**Result** ✓ Passed**MOT #10** 2017-05-13 08:28**MOT test number** 571141348507**Result** ✓ Passed**Advice** Offside Rear Inner Inner tyre on limit**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #9** 2017-05-13 08:28**MOT test number** 659053152280**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Inner Inner tyre on limit**MOT #8** 2016-05-15 07:57**MOT test number** 670935609089**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2015-05-20 08:56**MOT test number** 246630745180**Result** ✓ Passed**MOT #6** 2014-05-01 11:35**MOT test number** 268061724477**Result** ✓ Passed**Notice** Nearside rear tyre worn on edge

**MOT #5** 2014-04-30 15:32**MOT test number** 828010124152**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre worn on edge**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2013-04-23 09:42**MOT test number** 615613713197**Result** ✓ Passed**MOT #3** 2013-04-23 09:42**MOT test number** 638643613130**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2012-04-25 16:23**MOT test number** 517016312149**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-04-25 14:34
MOT test number	656706112123
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 September 2023

✓

MOT

Expires:
5 April 2025

Tax status	Expired at 1 September
Days left	242 days too late
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	EK09HTD
Plate since	2024-03-29
Current registration	EK09HTD
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2009-04-29
Last registration	2024-04-06
Complete history	See info



Registration #1	2009-04-29	27 mi
Registration #2	2012-04-25	56.340 mi
Registration #3	2012-04-25	56.340 mi
Registration #4	2013-04-23	75.043 mi
Registration #5	2014-04-30	97.315 mi
Registration #6	2014-05-01	97.315 mi
Registration #7	2015-05-20	106.489 mi
Registration #8	2016-05-15	111.668 mi
Registration #9	2017-05-13	123.204 mi
Registration #10	2017-05-13	123.204 mi
Registration #11	2018-04-18	131.802 mi
Registration #12	2019-04-06	136.810 mi
Registration #13	2020-04-06	151.277 mi
Registration #14	2020-04-06	151.277 mi
Registration #15	2020-04-06	151.277 mi
Registration #16	2020-04-06	151.277 mi
Registration #17	2020-04-06	151.277 mi
Registration #18	2020-04-06	151.277 mi
Registration #19	2020-04-06	151.277 mi
Registration #20	2020-04-06	151.277 mi
Registration #21	2020-04-06	151.277 mi
Registration #22	2020-04-06	151.277 mi
Registration #23	2020-04-06	151.277 mi
Registration #24	2020-04-06	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	090622085755BG