





report date: 2024-03-29

### General information

Make	KIA
Model	RIO 4 ISG
Colour	Black
Year of manufacture	2017
Top speed	114 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	107 BHP
Max. torque	137 Nm at 4.200 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 3

Date	2022-02-15	
Pictures	1	
Listing price	<u>View report</u>	



#### source: cargurus.co.uk

#### Entry 2

Date	2022-02-15
Pictures	0
Listing price	View report

#### source: autotrader.co.uk

#### Entry 1

Littly L		
Date	2021-11-09	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

Passed

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-26	
MOT pass rate	83 %	
MOT passed	5	
Failed MOT tests	1	
Total advice items	6	
Total items failed	3	

MOT #6	2024-01-15 14:18
MOT test number	380488378096
Result	✓ Passed
Next expiry date	2025-01-26

MOT #5	2023-01-18 12:50
MOT test number	230230467359
Result	✓ Passed

MOT #4	2022-01-26 09:43
MOT test number	302460965083
Result	<b>✓</b> Passed

MOT #3	2021-01-18 15:01

**MOT test number** 794896992335



Result

Central Front Items removed from driver's view prior to test sat nav moved and air freshener

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT #2** 2021-01-18 13:19

**MOT test number** 214716570656

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Central Front Items removed from driver's view prior to test sat nav moved and air freshener removed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm 1.4 mm (5.2.3 (e))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 1.8 mm (5.2.3 (e))

**MOT #1** 2020-01-22 10:48

**MOT test number** 131238968454

**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge AROUND 1.6MM (CENTRE) (5.2.3 (e))

**Advice** Items removed from driver's view prior to test

Advice Offside Front Tyre worn close to legal limit/worn on edge AROUND 1.6MM ( CENTRE) (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	26 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	IK SIN
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



LA66DBX report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-01-27
Last registration	2024-01-15
Complete history	See info



Registration #1	2017-01-27	19 mi
Registration #2	2020-01-22	19.993 mi
Registration #3	2021-01-18	27.189 mi
Registration #4	2021-01-18	27.190 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 es

More info >

CarCheck.co.uk page 10/11



LA66DBX report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4050 mm
Wheel base	2570 mm
Kerb weight	1236 kg
Max. allowed weight	1600 kg

## Additional information

Fuel tank capacity	43 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

**Engine number** G4FAGS035329