



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C220 CDI SE
Colour	Silver
Year of manufacture	2008
Top speed	142 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G





## MOT history

MOT expiry date	2021-11-25
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	24
Total items failed	10

MOT #19 2020-11-21 15:20

MOT test number 840367587635

Result ✓ Passed

Next expiry date 2021-11-25

- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18 2019-11-26 11:57

MOT test number 350745136309

Result ✓ Passed

- Advice** Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Brake pipe corroded, covered in grease or other material all pipes corroded (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #17** 2019-11-26 11:57**MOT test number** 288869775707**Result** ✗ Failed

- Advice** Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Brake pipe corroded, covered in grease or other material all pipes corroded (1.1.11 (c))
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #16** 2017-10-16 13:17**MOT test number** 847428106949**Result** ✓ Passed**MOT #15** 2017-10-11 15:45**MOT test number** 993074845432**Result** ✗ Failed

- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)

**MOT #14** 2017-04-26 14:24**MOT test number** 998339385386**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #13** 2017-04-21 14:52**MOT test number** 269778408915**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #12** 2016-11-11 14:57**MOT test number** 304432590071**Result** ✓ Passed**MOT #11** 2016-04-27 12:56**MOT test number** 240636542640**Result** ✓ Passed**MOT #10** 2016-04-22 11:45**MOT test number** 323638167704**Result** ✗ Failed

- Fail** Offside Front Front wheel bearing has excessive play (2.5.A.3c)
- Fail** Nearside Front Lower Front suspension has excessive play in a lower suspension ball joint rear joint (2.5.B.1a)

**MOT #9** 2015-10-29 12:47**MOT test number** 818709540912**Result** ✓ Passed

**MOT #8** 2015-04-29 09:53**MOT test number** 448169515186**Result** ✓ Passed**MOT #7** 2014-10-27 17:23**MOT test number** 687090504368**Result** ✓ Passed**MOT #6** 2014-04-04 12:53**MOT test number** 436414494094**Result** ✓ Passed**Notice** Nail in nearside front tyre**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2013-04-13 16:07**MOT test number** 819733103148**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #4** 2013-02-19 10:13**MOT test number** 505860253035**Result** ✓ Passed**MOT #3** 2012-02-20 15:39**MOT test number** 309801952094**Result** ✓ Passed



MOT #2

2011-10-20 17:45

MOT test number

528433291292

Result

✓ Passed

Notice

All brake pads are getting low

MOT #1

2011-10-20 16:51

MOT test number

578203591282

Result

✗ Failed

Fail

Nearside Upper Rear position lamp(s) not working (1.1.A.3b)

Notice

All brake pads are getting low



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>GY58XHP</b>
Plate since	2019-06-29
Current registration	<b>GY58XHP</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-10-29
Last registration	2020-11-21
Complete history	<a href="#">See info</a>



Registration #1	2008-10-29	7 mi
Registration #2	2011-10-20	78.345 mi
Registration #3	2011-10-20	78.345 mi
Registration #4	2012-02-20	79.932 mi
Registration #5	2013-02-19	82.586 mi
Registration #6	2013-04-13	84.552 mi
Registration #7	2014-04-04	94.000 mi
Registration #8	2014-10-27	119.408 mi
Registration #9	2015-04-29	133.447 mi
Registration #10	2015-10-29	146.990 mi
Registration #11	2016-05-20	151.377 mi
Registration #12	2016-05-20	151.377 mi
Registration #13	2016-05-20	151.377 mi
Registration #14	2016-05-20	151.377 mi
Registration #15	2016-05-20	151.377 mi
Registration #16	2016-05-20	151.377 mi
Registration #17	2016-05-20	151.377 mi
Registration #18	2016-05-20	151.377 mi
Registration #19	2016-05-20	151.377 mi
Registration #20	2016-05-20	151.377 mi

More info >



Dimensions & weight

Width	2020 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	64681130317672