



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D3 R-DESIGN LUX NAV
Colour	Grey
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	67.3 mpg
CO2 emission	111 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-10-21
Pictures	81
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #8	2023-11-02 14:16
MOT test number	102188807856
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2023-11-02 14:16
MOT test number	221119494744
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps rear both side (4.7.1 (b) (ii))

MOT #6	2022-10-31 14:37
MOT test number	717387017953
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #5** 2022-10-31 10:10**MOT test number** 275436696604**Result** ✗ Failed**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #4** 2021-10-26 14:03**MOT test number** 769748008858**Result** ✓ Passed**MOT #3** 2021-09-15 13:37**MOT test number** 644114999856**Result** ✓ Passed**MOT #2** 2020-12-17 10:57**MOT test number** 805899269736**Result** ✓ Passed**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #1** 2019-05-31 08:15**MOT test number** 478538032651**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KR16KKE
Plate since	2019-03-29
Current registration	KR16KKE
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-31
Last registration	2023-11-02
Complete history	See info



Registration #1	2016-05-31	19 mi
Registration #2	2019-05-31	39.787 mi
Registration #3	2020-12-17	55.738 mi
Registration #4	2021-09-15	80.538 mi
Registration #5	2023-05-31	95.277 mi
Registration #6	2023-05-31	95.277 mi
Registration #7	2023-05-31	95.277 mi
Registration #8	2023-05-31	95.277 mi
Registration #9	2023-05-31	95.277 mi
Registration #10	2023-05-31	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1663 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1593855