



report date: 2024-03-28

General information

Make	MINI
Model	COOPER
Colour	Silver
Year of manufacture	2017
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.499 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-06
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	4

MOT #7 2024-03-06 16:36

MOT test number 856605484017

Result ✓ Passed

Next expiry date 2025-03-06

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2024-03-06 14:21

MOT test number 571721243611

Result ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords not repairable (5.2.3 (d) (i))**Advice** All tyre walls cracking**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords not repairable (5.2.3 (d) (i))

MOT #5 2023-03-07 13:13

MOT test number 241585320028

Result ✓ Passed**Advice** All 4 tyre walls cracking

**MOT #4** 2023-03-07 13:13**MOT test number** 571391594132**Result** ✗ Failed**Advice** All 4 tyre walls cracking**Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #3** 2022-03-03 17:02**MOT test number** 555443026208**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2021-03-06 09:29**MOT test number** 431756767789**Result** ✓ Passed**MOT #1** 2020-02-03 13:48**MOT test number** 708473441473**Result** ✓ Passed**Advice** Front wipers starting to smear**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-02-25
Last registration	2024-03-06
Complete history	See info



Registration #1	2017-02-25	14 mi
Registration #2	2020-02-03	14.921 mi
Registration #3	2021-03-06	15.906 mi
Registration #4	2022-03-03	18.229 mi
Registration #5		
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1160 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	G047H444
---------------	----------