





report date: 2024-03-29

### General information

| Make                | LAND ROVER                               |
|---------------------|--|
| Model               | RANGE ROVER EVOQUE S D AUTO R-DYNAMIC SE |
| Colour              | Grey                                     |
| Year of manufacture | 2019                                     |
| Top speed           | 122 mph                                  |
| Gearbox             | 9 speed automatic                        |

# Engine & fuel consumption

| Power                  | 148 BHP             |
|------------------------|---------------------|
| Max. torque            | 380 Nm at 2.500 rpm |
| <b>Engine capacity</b> | 1.999 сс            |
| Cylinders              | 4                   |
| Fuel type              | Diesel              |
| Consumption combined   | 42.2 mpg            |
| CO2 emission           | 149 g/km            |
| CO2 label              | F                   |



CarCheck.co.uk page 1/10



report date: 2024-03-29

# Internet history

### Entry 2

Date 2022-01-18

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

| Date 2022-01-18 |  |
|-----------------|--|
|-----------------|--|

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

# MOT history

| MOT expiry date    | 2025-01-20 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 5          |
| Total items failed | 0          |

| MOT #3           | 2024-01-09 15:40 |
|------------------|------------------|
| MOT test number  | 831944997310     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-01-20       |

| MOT #2   |  | 2023-01-16 14:50 |
|----------|--|------------------|
| MOT test | number   | 518706428175     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                |                  |
| Advice   | Front Exhaust mounting defective rubber split in two (6.1.2 (a))                     |                  |
| Advice   | Coolant level low  |                  |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))               |                  |
| Advice   | Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |                  |

| MOT #1          | 2022-01-21 12:04 |
|-----------------|------------------|
| MOT test number | 381359712902     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/10



### Tax & MOT check



| Tax status       | Valid until 1 January |
|------------------|-----------------------|
| Days left        | 246                   |
| MOT expiry date  | 20 January 2025       |
| Full MOT history | See MOT history       |

### Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | Н          |
| First licence fee (12 months)                        | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 4/10



report date: 2024-03-29

### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



furthe scinors

YF19WXA

report date: 2024-03-29

# Owner history For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this LAND ROVER had different number plates.

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2019-04-13 |
| Last registration          | 2024-01-09 |
| Complete history           | See info   |



| Registration #1 | 2019-04-13 | 14 mi     |
|-----------------|------------|-----------|
| Registration #2 |            | 77,777 66 |
| Registration #3 |            | 9.79 66   |
| Registration #4 |            | 11.777 66 |
| Registration #5 |            | 11.777 es |
| Posistration #6 |            |           |

Registration #6

More info >

CarCheck.co.uk page 9/10



Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 94%             |
| Children       | 87%             |
| Pedestrian     | 72%             |
| Safety systems | 73%             |
| Overall rating | 84%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 2100 mm |
|---------------------|---------|
|                     |         |
| Height              | 1649 mm |
|                     |         |
|                     | 4074    |
| Length              | 4371 mm |
| •                   |         |
| Many allamadonalula | 2400 1  |
| Max. allowed weight | 2490 kg |

# Additional information

| Number of seats | 5                 |
|-----------------|-------------------|
| Number of axles | 2                 |
| Engine number   | 190215W0004204DTD |

CarCheck.co.uk page 10/10