





General information

| Make | HYUNDAI |
|---------------------|---------------------------|
| Model | 140 CRDI STYLE BLUE DRIVE |
| Colour | Silver |
| Year of manufacture | 2012 |
| Top speed | 124 mph |
| 0 - 60 mph | 10.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 325 Nm at 2.500 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |







Internet history

Entry 2

Date Pictures 2023-05-22

12

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-09-06 15

View report

source: autotrader.co.uk









MOT history

| MOT expiry date | 2024-06-26 |
|--------------------|------------|
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 26 |
| Total items failed | 4 |

| MOT #13 | 2023-06-27 08:37 |
|------------------|------------------|
| MOT test number | 252673462863 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-26 |

| MOT #12 | 2023-06-27 08:37 | |
|-------------------------|---|--|
| MOT test number | 487213107955 | |
| Result | × Failed | |
| Pass with rectification | Offside Rear Service brake excessively binding (1.2.1 (f)) | |
| Pass with rectification | Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Pass with rectification | Offside Front Headlamp aim too high (4.1.2 (a)) | |

| MOT #11 | 2022-08-24 13:14 |
|-----------------|------------------|
| MOT test number | 327915556212 |
| Result | ✓ Passed |





| MOT #10 | | 2022-08-12 10:03 |
|----------|---|------------------|
| MOT test | number | 302757887063 |
| Result | | 🗙 Failed |
| MAJOR | Offside Front Headlamp light intensity severely reduced (4.1.4 (a)) | |
| MAJOR | Steering column top bearing excessively worn (2.2.2 (b)) | |
| MAJOR | Front Exhaust system insecure mounting not connected (6.1.2 (a)) | |
| MAJOR | Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |

| MOT #9 | | 2021-07-27 14:54 |
|----------|---|------------------|
| MOT test | number | 746321289284 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #8 | | 2021-07-26 08:18 |
|----------|--|------------------|
| MOT test | number | 452486859117 |
| Result | | × Failed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 | (a) (ii)) |
| MAJOR | Offside Front Service brake lagging in operation (1.2.1 (d)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| MAJOR | Steering column universal joint has excessive wear or play (2.2.2 (c)) | |
| Advice | Front Brake pad(s) wearing thin very low (1.1.13 (a) (ii)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |





| MOT #7 | | 2020-08-08 07:33 |
|--|---|---------------------|
| MOT test r | number | 861252351117 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (| 5.2.3 (e)) |
| MOT #6 | | 2019-08-06 11:48 |
| MOT test r | number | 989343134967 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge badly worn inner edge close to cords and split close to cords (5.2.3 (e)) | | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice (5.2.3 (e)) | Offside Rear Tyre worn close to legal limit/worn on edge badly worn inner | edge close to cords |

| MOT #5 | | 2018-08-01 09:52 |
|------------|---|------------------|
| MOT test i | number | 347258645288 |
| Result | | ✓ Passed |
| Advice | Exhaust mounting defective (6.1.2 (a)) | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Both rear tyres badly worn inner edges | |

| 2017-08-09 07:04 |
|------------------|
| 375272551342 |
| ✓ Passed |
| |
| |





| MOT #3 | 2016-08-11 08:04 |
|---|------------------|
| MOT test number | 278200245413 |
| Result | ✓ Passed |
| Advice Brake disc worn, pitted or scored, but not seriously weakened both fronts (3 | 8.5.1i) |
| Advice Both front tyres wearing inner edges | |
| Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b) | |
| Advice Offside Front Brake pad(s) wearing thin (3.5.1g) | |
| | |
| MOT #2 | 2015-08-14 13:26 |
| MOT test number | 795142968623 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2015-08-13 15:09 |
| MOT test number | 337265725486 |
| Result | × Failed |
| Fail Nearside Front wheel bearing has excessive play (2.5.A.3c) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 June 2024 | ✓ MOT Expires: 26 June 2024 |
|---------------------------------------|--------------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 26 June 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| - |
|-----|
| AMP |
| |
| |
| - A |
| |
| |
| |
| |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|--|-------------|
| ********* | |
| ******** | |
| ******* | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| | |
| Current registration | |







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 16 |
| First mileage registration | 2012-10-24 |
| Last registration | 2023-06-27 |
| Complete history | <u>See info</u> |



| Registration #1 | 2012-10-24 | 12 mi |
|---|--|---|
| Registration #2 | 2015-08-13 | 37.514 mi |
| Registration #3 | 2015-08-14 | 37.516 mi |
| Registration #4 | 2016-08-11 | 47.194 mi |
| Registration #5 | 2017-08-09 | 57.429 mi |
| Registration #6 | 2018-08-01 | 65.463 mi |
| Registration #7 | 2019-08-06 | 70.774 mi |
| Registration #8 | 2020-08-08 | 84.257 mi |
| | 2020 00 00 | |
| Registration #9 | mm.m.m | 11.777 mi |
| | 1010 00 00 1010 00 00 1010 00 00 | 11.227 est |
| Registration #9 | 1010 00 00 1010 00 00 1010 00 00 1010 00 00 1010 00 00 | 01.000 est 01.000 est 01.000 est |
| Registration #9 Registration #10 | 1010 00 00 1010 00 00 1010 00 00 1010 00 00 1010 00 00 1010 00 00 1010 00 00 | 00.000 est 01.000 est 00.000 est 01.000 est |
| Registration #9 Registration #10 Registration #11 | 1010 00 00 1010 00 00 | 00.000 est 0.000 est 00.000 est 00.000 est 00.000 est |
| Registration #9 Registration #10 Registration #11 Registration #12 | 1010 00 00 1010 00 1000 00 100 | 00.000 460 01.000 460 01.000 460 01.000 460 01.000 460 01.000 460 |
| Registration #9 Registration #10 Registration #11 Registration #12 Registration #13 | 1010000 101000 10000 10000 10000 10000 10000 10000 10000 10000 10000 100000 100000 100000 100000 100000 | 00.000 440 0.000 440 0.000 440 0.000 440 0.000 440 0.000 440 0.000 440 0.000 440 |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| \$0482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 86% |
| Pedestrian | 43% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1815 mm |
| Height | 1470 mm |
| Length | 4770 mm |
| Wheel base | 2770 mm |
| Kerb weight | 1648 kg |
| Max. allowed weight | 2120 kg |
| Additional information | |
| Fuel tank capacity | 70 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 13/13 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | D4FDCU154091 |