




report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L2 TIPPER HDI
Colour	White
Year of manufacture	2017
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.5 mpg
CO2 emission	229 g/km
CO2 label	L






Internet history

Entry 1

Date	2022-02-24
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-14
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	5

## MOT #8 2024-03-13 10:13

MOT test number 343476455346

Result ✓ Passed

Next expiry date 2025-03-14

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

## MOT #7 2023-03-13 10:21

MOT test number 842305797087

Result ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

## MOT #6 2022-03-15 16:25

MOT test number 842198216287

Result ✓ Passed

**MOT #5** 2021-04-14 07:42**MOT test number** 744828696059**Result** ✓ Passed**Advice** Nearside Rear Valve stem slightly damaged Perished (5.2.3 (j))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #4** 2021-04-14 07:42**MOT test number** 278888156061**Result** ✗ Failed**Pass with rectification** Headlamp aim too low Both (4.1.2 (a))**Advice** Nearside Rear Valve stem slightly damaged Perished (5.2.3 (j))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2020-05-12 10:03**MOT test number** 359823614207**Result** ✓ Passed**Advice** Nearside Front Valve stem slightly damaged Perished (5.2.3 (j))**MOT #2** 2020-05-12 08:11**MOT test number** 849590802988**Result** ✗ Failed**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**Advice** Nearside Front Valve stem slightly damaged Perished (5.2.3 (j))**Fail** Windscreen wiper does not clear the windscreen effectively Blades excessively split (3.4 (b) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))



MOT #1	2020-04-15 12:12
MOT test number	646037550440
Result	✓ Passed
Advice	COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 March 2025

Tax status		Valid until 1 September
Days left		126
MOT expiry date		14 March 2025
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-04-24
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2017-04-24	10 mi
Registration #2	2020-05-12	42.811 mi
Registration #3	2020-05-12	42.811 mi
Registration #4	2021-04-14	51.619 mi
Registration #5	2021-04-14	51.619 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2023-05-20	55.277 mi
Registration #9	2024-03-13	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2167 mm
Height	2440 mm
Length	5593 mm
Wheel base	3450 mm
Kerb weight	2265 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	TRJA0949658