





report date: 2024-03-29

#### General information

Male	ALIDI
Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Grey
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	240 BHP
Max. torque	550 Nm at 1.500 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	260 g/km
CO2 label	M



CarCheck.co.uk page 1/12



## Internet history

## Entry 2

Date 2021-10-22

Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-01-22

Pictures 26

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-04-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #15	2023-04-06 10:26
MOT test number	475281133983
Result	✓ Passed
Next expiry date	2024-04-05

MOT #14	2023-04-06 08:55
MOT test number	897860910813
Result	<b>X</b> Failed
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Fail Parking brake inoperative on one side both sides (1.4.1 (a))	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #13	2021-08-24 17:21
MOT test number	299548651515
Result	✓ Passed
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #12	2020-06-06 11:26
MOT test number	816864298970
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



MOT #11 2020-06-06 11:26

MOT test number 356749502825

**Result** X Failed

Pass with rectification Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Pass with rectification** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #10 2018-10-22 10:03

MOT test number 475134890289

**Result** 
✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2017-10-19 09:39

**MOT test number** 832161287565

Result \( \sqrt{Passed} \)

**MOT #8** 2016-09-29 08:04

MOT test number 878929424005

Result \rightarrow Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2015-10-28 00:00

**MOT test number** 563465667257

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' stone chip "B"

(8.3.1d)

MOT #6 2014-10-20 17:31

**MOT test number** 278683494292

CarCheck.co.uk page 4/12



MOT #5 2014-01-21 13:05

**MOT test number** 166301624092

**Result** ✓ Passed

MOT #4 2014-01-20 12:10

**MOT test number** 435720124091

**Result** X Failed

**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #3 2013-01-23 12:12

**MOT test number** 837643823059

**Result** ✓ Passed

MOT #2 2012-01-23 10:27

**MOT test number** 897743822066

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2011-01-28 12:14

MOT test number 819918021083

Result \( \sqrt{Passed} \)

**Advice** Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax expired: 30 September 2023

# X MOT

Expired: 5 April 2024

Tax status	Expired at 30 September
Days left	213 days too late
MOT expiry date	5 April 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when misterly		
For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		/e?
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-02
Last registration	2023-04-06
Complete history	See info



Registration #1	2008-01-02	24 mi
Registration #2	2011-01-28	36.158 mi
Registration #3	2012-01-23	45.033 mi
Registration #4	2013-01-23	52.889 mi
Registration #5	2014-01-20	60.357 mi
Registration #6	2014-01-21	60.368 mi
Registration #7	2014-10-20	67.547 mi
Registration #8	2015-10-28	79.440 mi
Registration #9	2016-09-29	91.362 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

# Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

Engine number CAS 025689