





General information

Make	MAZDA
Model	5 TS2
Colour	Gold
Year of manufacture	2009
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I







Internet history

Entry 1	
Date	2022-02-06
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-18
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	24
Total items failed	1

MOT #14	2024-04-19 12:40
MOT test number	201678688693
Result	✓ Passed
Next expiry date	2025-04-18
Advice General underside surface rust	

MOT #13		2023-02-21 12:00
MOT test	number	552029650891
Result		✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Anti-roll bar linkage ball joint has slight play both rear (5.3.4 (a) (i))	
Advice	General underbody corrosion	





MOT #12	2022-02-01	08:48
MOT test i	number 6493954	55516
Result	🗸 F	Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.	4 (a)
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3	3.4

MOT #11		2021-02-05 09:04
MOT test	number	520610721802
Result		✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exces	sive movement (5.3.4 (a)
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4

MOT #10	2020-01-30 08:48
MOT test number	715270676034
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

МОТ #9		2020-01-30 08:48
MOT test number		897050605064
Result		🗙 Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		





MOT #8		2019-01-29 09:03
MOT test num	ber	250431423370
Result		✓ Passed
MOT #7		2018-01-29 09:04
MOT test num	ber	688980651647
Result		Passed
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		
Advice Nea	Advice Nearside and offside rear tyre feathering on inner edge	
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		
Advice Offs	side Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #6	2017-02-23 08:52
MOT test number	377535677390
Result	✓ Passed

MOT #5	2016-02-25 13:52
MOT test number	538192482459
Result	✓ Passed

MOT #4		2015-03-12 09:12
MOT test	number	856281375003
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Slight play in steering rack	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	





MOT #3	2014-03-26 09:09
MOT test number	907615284031
Result	✓ Passed
MOT #2	2013-03-27 11:49
MOT test number	316056183018
Result	✓ Passed
MOT #1	2012-01-25 11:10
MOT test number	307615222042
Result	✓ Passed

CarCheck.co.uk



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 July 2024	Expires: 18 April 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-02-09
Last registration	2024-04-19
Complete history	See info



Registration #1	2009-02-09	15 mi
Registration #2	2012-01-25	12.647 mi
Registration #3	2013-03-27	19.083 mi
Registration #4	2014-03-26	24.468 mi
Registration #5	2015-03-12	29.341 mi
Registration #6	2016-02-25	36.638 mi
Registration #7	2017-02-23	43.201 mi
Registration #8	2018-01-29	48.006 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		



DN58CPX report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2110 kg
Additional information	
Additional information Fuel tank capacity	60 I
	60 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5