





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Silver
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history


Entry 1

Date 2022-01-23


Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-11
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #10	2023-11-10 12:13
MOT test number	235302575501
Result	✓ Passed
Next expiry date	2024-11-11
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3	3 (e))
Advice Central Rear Seat belt buckle slightly damaged Plastic Casing missir	ng (7.1.2 (d))
Advice Under-Trays fitted front-rear	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear, Just within limit at time of test will require attention soon (5.3.4 (a) (i))	

MOT #9	2022-11-10 17:11
MOT test number	638357935472
Result	✓ Passed
Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulti (5.3.4 (a) (i))	ng in excessive movement

MOT #8	2021-11-12 10:38
MOT test number	614296066596
Result	✓ Passed
MOT #7	2020-11-06 13:21
MOT test number	249797073585
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2019-11-12 09:39

MOT test number 396446630018

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2018-10-23 08:38

MOT test number 826058599815

Result ✓ Passed

MOT #4 2017-11-10 13:57

MOT test number 203866234037

Result ✓ Passed

MOT #3 2016-10-24 12:37

MOT test number 134422195193

Result ✓ Passed

MOT #2 2015-10-24 08:23

MOT test number 395558888605

Result

Passed

Advice Both front tyres bald on inner edges and small cuts in tread

MOT #1 2014-10-15 12:58

MOT test number 345988184406

Result
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	11 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Date		
Category		

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-12-15
Last registration	2023-11-10
Complete history	See info



Registration #1	2011-12-15	21 mi
Registration #2	2014-10-15	31.970 mi
Registration #3	2015-10-24	41.929 mi
Registration #4	2016-10-24	48.101 mi
Registration #5	2017-11-10	55.003 mi
Registration #6	2018-10-23	63.917 mi
Registration #7		9.77 es
Registration #8		11.777 es
Registration #9		9.77 66
Registration #10		11.777 es
Registration #11		9.77 66
Registration #12		0.777 44

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

CarCheck.co.uk page 11/11

Number of axles	2

Engine number CAY 586764