





report date: 2024-03-29

General information

Make	HONDA
Model	CIVIC I-DTEC SR
Colour	Grey
Year of manufacture	2015
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	А



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2023-02-17

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2023-02-15	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

Entry 1

Date 2021-05-22	
-----------------	--

Pictures 37

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

✓ Passed

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

Result

MOT expiry date	2025-02-27
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #8		2024-02-22 10:57
MOT test	number	455316695938
Result		✓ Passed
Next expi	y date	2025-02-27
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively n/s and o/s (1.1.14 (a) (i))	

MOT #7	2023-02-28 14:19
MOT test number	600882175328
Result	✓ Passed
MOT #6	2022-05-11 11:31
MOT test number	681395383222
Result	✓ Passed
MOT #5	2021-05-20 08:23
MOT test number	888210186404

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-05-20 08:23

MOT test number 580751298803

Result X Failed

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #3 2020-12-17 11:10

MOT test number 208006128113

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2019-11-22 11:29

MOT test number 902854486727

Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice TPMS warning on dash indicating low tyre pressure

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2018-11-27 11:20

MOT test number 280169877932

Result ✓ Passed

Minor Offside Windscreen wiper blade defective smearing (3.4 (b) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



DC65EXU report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HONDA had different number plates. deer of plates furthe scinors

CarCheck.co.uk page 8/11



DC65EXU report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-12-18
Last registration	2024-02-22
Complete history	See info



2015-12-18	28 mi
2018-11-27	25.882 mi
2019-11-22	35.489 mi
2020-12-17	41.885 mi
2021-05-20	47.297 mi
2021-05-20	47.297 mi
	11.777 es
	2018-11-27 2019-11-22 2020-12-17 2021-05-20

More info >

CarCheck.co.uk page 10/11



DC65EXU report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	94%
Children	83%
Pedestrian	69%
Safety systems	86%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1470 mm
Length	4370 mm
Wheel base	2595 mm
Kerb weight	1425 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A13011532

CarCheck.co.uk page 11/11