



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	279 Nm at 1.900 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E





MOT history

MOT expiry date	2024-02-22
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	18

MOT #16	2023-02-17 17:11
MOT test number	484006109125
Result	✓ Passed
Next expiry date	2024-02-22
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2022-02-23 15:50
MOT test number	763319054190
Result	✓ Passed

MOT #14	2021-02-06 13:52
MOT test number	643082019494
Result	✓ Passed

MOT #13	2020-02-18 11:01
MOT test number	292416528171
Result	✓ Passed
Advice	Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2020-02-16 12:16**MOT test number** 455156213042**Result** ✗ Failed

- Fail** Nearside Front Headlamp aim too low and too far to the right. and o/s/f (4.1.2 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Central Rear Exhaust silencer insecure exhaust shield (8.1.1 (b) (i))
- Fail** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users and cigarette lighter in operative to test idle speed (8.2.2.2 (c))

MOT #11 2019-02-01 09:21**MOT test number** 535201877581**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2018-01-31 14:38**MOT test number** 312623099117**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2018-01-31 11:59**MOT test number** 400653416876**Result** ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2017-01-20 09:31

MOT test number

280154138002

Result

✓ Passed

- Advice** Nearside Rear tyre slightly perished
- Advice** Central Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Direction indicator slightly discoloured starting to flash white (1.4.A.2f)
- Advice** Offside Rear tyre slightly perished

MOT #7

2017-01-19 11:02

MOT test number

773659529854

Result

✗ Failed

- Advice** Offside Rear Brake pad(s) wearing thin 30% remaining (3.5.1g)
- Advice** Nearside Rear tyre slightly perished
- Fail** Offside Front front brake excessively fluctuating (3.7.B.3)
- Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement lower arm rear bush (2.4.G.2)
- Fail** Offside Front Inner brake disc in such a condition that it is seriously weakened heavily corroded (3.5.1i)
- Fail** Offside Front Tyre has ply or cords exposed inner edge of tyre (4.1.D.1b)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick 5% remaining (3.5.1g)
- Advice** Offside Rear Direction indicator slightly discoloured starting to flash white (1.4.A.2f)
- Advice** Offside Rear tyre slightly perished
- Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement lower arm rear bush (2.4.G.2)
- Advice** Central Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

MOT #6

2016-02-19 14:40

MOT test number

532477679846

Result

✓ Passed

**MOT #5** 2015-09-08 16:48**MOT test number** 694239421376**Result** ✓ Passed**MOT #4** 2015-09-07 06:56**MOT test number** 610715794145**Result** ✗ Failed

- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Fail** Nearside Rear brake caliper has restricted free movement parking brake (3.5.1k)
- Advice** Exhaust heat shield loose
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #3 2014-09-08 07:45**MOT test number** 899001854228**Result** ✓ Passed**MOT #2** 2013-09-30 14:47**MOT test number** 648293873271**Result** ✓ Passed**MOT #1** 2012-09-26 11:40**MOT test number** 977430372251**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2023

X

MOT

Expired:
22 February 2024

Tax status	Expired at 1 March 2023
Days left	425 days too late
MOT expiry date	22 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SV09GKA
Plate since	2019-09-29
Current registration	SV09GKA
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-19
Last registration	2023-02-17
Complete history	See info



Registration #1	2009-06-19	17 mi
Registration #2	2012-09-26	26.621 mi
Registration #3	2013-09-30	34.149 mi
Registration #4	2014-09-08	40.414 mi
Registration #5	2015-09-07	47.137 mi
Registration #6	2015-09-08	47.137 mi
Registration #7	2016-02-19	49.428 mi
Registration #8	2017-01-19	59.719 mi
Registration #9	2017-01-20	59.721 mi
Registration #10	2019-05-29	59.721 mi
Registration #11	2019-05-29	59.721 mi
Registration #12	2019-05-29	59.721 mi
Registration #13	2019-05-29	59.721 mi
Registration #14	2019-05-29	59.721 mi
Registration #15	2019-05-29	59.721 mi
Registration #16	2019-05-29	59.721 mi
Registration #17	2019-05-29	59.721 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1279 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U56246