




report date: 2024-03-28

General information

Make	MINI
Model	COOPER S AUTO COOPER S
Colour	Blue
Year of manufacture	2012
Top speed	138 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 4.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	55.4 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-02
Pictures	10
Listing price	View report

SMC

Sheffield Motor Company



Finance

£256.84

per month

HP REPRESENTATIVE EXAMPLE	
CASH PRICE	£11,795.00
DEPOSIT	£2.00
TOTAL AMOUNT OF CREDIT	£11,793.00
TOTAL AMOUNT PAYABLE	£15,415.40
ADMINISTRATION FEE	£2.00
OPTION TO PURCHASE FEE	£1.00
FIXED INTEREST RATE	6.49% p.a.
REPRESENTATIVE APR	6.36% APR
DURATION OF AGREEMENT	60 MONTHS
INITIAL PAYMENT	£150.84
60 MONTHLY PAYMENTS	£256.84
FINAL PAYMENT	£237.84

Small text disclaimer at the bottom of the finance table.



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	37
Total items failed	3

MOT #11 2023-07-01 08:31

MOT test number 546155481528

Result ✓ Passed

Next expiry date 2024-06-30

- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.9mm+ (5.2.3 (e))
- Advice** Rear Tyre has a cut but not deep enough to reach the ply or cords both cut outer sidewalls (5.2.3 (d) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords cut outer sidewall (5.2.3 (d) (i))

MOT #10 2022-08-15 10:45

MOT test number 135728906997

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs lipped (1.1.14 (a) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Tyre has a cut but not deep enough to reach the ply or cords n/s/f, n/s/r & o/s/r outer sidewall (5.2.3 (d) (i))
- Advice** Front Inner Brake pad(s) wearing thin 2-3mm+ (1.1.13 (a) (ii))



MOT #9	2021-07-12 13:03
MOT test number	183466444635
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #8	2020-09-15 13:39
MOT test number	750541540537
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge heavily worn on edges (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #7**

2020-09-10 11:50

MOT test number

833860474012

Result**✗ Failed****Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm Tyre out of shape in multiple places (5.2.3 (e))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Offside Front Tyre worn close to legal limit/worn on edge heavily worn on edges (5.2.3 (e))

MOT #6

2019-10-07 14:26

MOT test number

684475632797

Result**✓ Passed****Advice**

Offside Front tyre damaged on side wall

Advice

Rear Tyre worn close to legal limit/worn on edge both very strong advise (5.2.3 (e))

Advice

Front number plate broken

**MOT #5** 2019-10-07 11:52**MOT test number** 157525427505**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front tyre damaged on side wall**Advice** Rear Tyre worn close to legal limit/worn on edge both very strong advise (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front number plate broken**MOT #4** 2018-09-18 09:08**MOT test number** 414475996300**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #3** 2017-09-20 08:50**MOT test number** 815665916173**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2016-09-14 11:27**MOT test number** 586224051119**Result** ✓ Passed**Advice** Nearside front tyre is bald on edges/sidewalls are perished and cut/no cord**Advice** Offside front tyre bald on edges/sidewalls badly perished and cuts/no cord



MOT #1	2015-09-21 11:47
MOT test number	370357669477
Result	✓ Passed
Advice	Rear seatbelts not checked as child seats fitted
Advice	Nearside Front tyre worn on outer edge



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-10-12
Last registration	2023-07-01
Complete history	See info



Registration #1	2012-10-12	12 mi
Registration #2	2015-09-21	10.986 mi
Registration #3	2016-09-14	14.532 mi
Registration #4	2017-09-20	18.759 mi
Registration #5	2018-09-18	22.648 mi
Registration #6	2019-10-07	27.613 mi
Registration #7	2019-10-07	27.613 mi
Registration #8	2019-10-07	27.613 mi
Registration #9	2019-10-07	27.613 mi
Registration #10	2019-10-07	27.613 mi
Registration #11	2019-10-07	27.613 mi
Registration #12	2019-10-07	27.613 mi
Registration #13	2019-10-07	27.613 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1205 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2

Engine number	A840J328
---------------	----------