





### General information

Make	BMW
Model	525 525D SPORT TOURING
Colour	Grey
Year of manufacture	2005
Top speed	139 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	177 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.497 сс
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	43.5 mpg
Consumption combined	35.3 mpg
CO2 emission	213 g/km
CO2 label	К





## MOT history

MOT expiry date	2021-11-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	19
Total items failed	6

MOT #17	2020-12-01 11:42
MOT test number	768696183396
Result	✓ Passed
Next expiry date	2021-11-30
Advice Hand brake just passed limits	

MOT #16	2020-11-24 14:55
MOT test number	563256776014
Result	🗙 Failed
Advice Hand brake just passed limits	
Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>Fail</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #15	2019-07-16 11:20
MOT test number	443614818919
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #14	2019-07-15 10:23
MOT test number	164895795112
Result	🗙 Failed
AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))FailSupplementary restraint system warning lamp indicates a fault (7.1.6 (a))	

MOT #13	2018-07-25 13:18
MOT test number	441036151692
Result	✓ Passed

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12	2018-07-20 08:47
MOT test number	261461963082
Result	× Failed
Fail Offside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))   Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #11	2017-07-25 14:31
MOT test number	853734442581
Result	Passed
Advice Offside Front Lower Suspension arm has slight play in a ball joint rear	arm (2.4.G.2)

MOT #10	2017-07-20 11:20
MOT test number	109063656499
Result	🗙 Failed
Advice Offside Front Lower Suspension arm has slight play in a ball joint rear arm (2.4.0	G.2)
<b>Fail</b> Front Brake pipe excessively corroded to rear by tank area (3.6.B.2c)	





MOT #9		2016-07-28 07:31
MOT test	number	742119207599
Result		Passed
Advice Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1) Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #8		2015-07-06 09:10
MOT test	number	559277585160
Result		🗸 Passed

MOT #7	2014-07-09 16:06
MOT test number	298640194137
Result	✓ Passed

MOT #6	2013-07-29 15:58
MOT test number	629670413224
Result	✓ Passed

MOT #5	2013-07-27 11:38
MOT test number	679218903249
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
<b>Fail</b> Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	





MOT #4		2012-07-20 12:44
MOT test	number	857342002254
Result		✓ Passed
Notice	Front tyres wearing on inner edges	
Notice	Oil leak from sump plug area	
Notice	O/S/R tyre worn on inner edge	
MOT #3		2011-03-03 11:20
MOT test	number	256202761012
Result		✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt		
Notice	O/s/r suspension has loud squeek, appears to come from anti roll link arm bu	t no wear evident

**Notice** Pad wear indicator is on but pads in good order (approx 3 to 4mm)

**Notice** O/s/r, o/s/f and n/s/f tyres all slightly feathered on inner edges

**Notice** Front discs slightly worn

MOT #2	2009-11-03 09:43
MOT test number	200627009367
Result	✓ Passed
MOT #1	2008-03-19 10:22
MOT test number	310559378003

Result

🗸 Passed





Tax & MOT check

X Untaxed	× мот
<b>Tax expired:</b> 1 February 2021	Expired: 30 November 2021
Tax status	Expired at 1 February 2021
Days left	1183 days too late
MOT expiry date	30 November 2021
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lampe
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-06-27
Last registration	2020-12-01
Complete history	<u>See info</u>



Registration #1	2005-06-27	21 mi
Registration #2	2008-03-19	17.429 mi
Registration #3	2009-11-03	36.477 mi
Registration #4	2011-03-03	52.223 mi
Registration #5	2012-07-20	61.745 mi
Registration #6	2013-07-27	70.316 mi
Registration #7	2013-07-29	70.316 mi
Registration #8	2014-07-09	78.738 mi
Registration #9	2015-07-06	86.871 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 esi





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1846 mm
Height	1491 mm
Length	4843 mm
Wheel base	2886 mm
Max. allowed weight	2285 kg
Additional information	
Evel tank conscitu	
Fuel tank capacity	70
Fuel delivery	70 l Direct Injection
Fuel delivery	Direct Injection

**Engine number** 

26306077