



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 S
Colour	Silver
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	120 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-05
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #22	2021-08-02 15:33
MOT test number	889634789424
Result	✓ Passed
Next expiry date	2022-08-01
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #21	2020-08-28 15:42
MOT test number	747224240866
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Valve stem slightly damaged (5.2.3 (j))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #20**

2020-08-28 09:47

MOT test number

267420507614

Result**✗ Failed**

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19**

2019-09-03 08:39

MOT test number

863177697028

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #18

2019-09-03 08:21

MOT test number

447200402335

Result

✗ Failed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2018-09-11 08:05

MOT test number

205335327921

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases And Rear (6.1.2 (a))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #16

2017-09-12 10:18

MOT test number

133071652923

Result

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Exhaust has a minor leak of exhaust gases corroded on joints (7.1.2)
- Advice** Offside Front coil spring corroded (2.4.C.1b)

**MOT #15**

2017-09-12 10:18

MOT test number

641206737198

Result**✗ Failed**

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Pass with rectification** Nearside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
- Advice** Exhaust has a minor leak of exhaust gases corroded on joints (7.1.2)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)

MOT #14

2016-09-15 14:16

MOT test number

817559691685

Result**✓ Passed**

- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front coil spring corroded (2.4.C.1b)

MOT #13

2015-08-28 09:22

MOT test number

218550545214

Result**✓ Passed**

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #12** 2014-08-27 13:36**MOT test number** 956549934239**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-08-27 10:05**MOT test number** 675619434236**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #10** 2013-08-28 09:51**MOT test number** 155880543272**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)

**MOT #9** 2013-08-28 09:51**MOT test number** 127010943276**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #8** 2012-08-29 12:31**MOT test number** 435512242204**Result** ✓ Passed**MOT #7** 2011-08-22 13:48**MOT test number** 906994531228**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2011-08-22 10:08**MOT test number** 109244931261**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside brake caliper securing device missing (3.5.1j)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-08-16 15:23**MOT test number** 243818220239**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2009-08-26 09:38**MOT test number** 324608339424**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2009-08-26 09:38**MOT test number** 123768339217**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Offside Registration plate lamp not working (1.1.5c)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2008-08-27 10:11**MOT test number** 964170248285**Result** ✓ Passed**MOT #1** 2007-08-17 09:29**MOT test number** 673219227287**Result** ✓ Passed



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-29
Current registration	XXXX XX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-09-01
Last registration	2021-08-02
Complete history	See info



Registration #1	2004-09-01	19 mi
Registration #2	2007-08-17	22.286 mi
Registration #3	2008-08-27	27.447 mi
Registration #4	2009-08-26	34.753 mi
Registration #5	2010-08-16	40.743 mi
Registration #6	2011-08-22	43.209 mi
Registration #7	2011-08-22	43.214 mi
Registration #8	2012-08-29	46.014 mi
Registration #9	2013-08-28	51.556 mi
Registration #10	2014-08-27	56.600 mi
Registration #11	2014-08-27	56.600 mi
Registration #12	2015-08-27	61.643 mi
Registration #13	2016-08-27	66.686 mi
Registration #14	2017-08-27	71.729 mi
Registration #15	2018-08-27	76.772 mi
Registration #16	2019-08-27	81.815 mi
Registration #17	2020-08-27	86.858 mi
Registration #18	2021-08-27	91.901 mi
Registration #19	2022-08-27	96.944 mi
Registration #20	2023-08-27	101.987 mi
Registration #21	2024-08-27	107.030 mi
Registration #22	2025-08-27	112.073 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FSR94900767