



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	Black
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-07-23
Pictures	29
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-25
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	39
Total items failed	2

MOT #18	2023-07-26 11:37
MOT test number	736618408230
Result	✓ Passed
Next expiry date	2024-07-25

MOT #17	2023-07-22 11:13
MOT test number	545725908502
Result	✗ Failed
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))
DANGEROUS	Offside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))
DANGEROUS	Nearside Rear Tyre has ply or cords damaged inner edge (5.2.3 (d) (ii))

MOT #16	2022-07-08 11:17
MOT test number	766757199483
Result	✓ Passed

MOT #15	2022-07-07 09:27
MOT test number	639149765525
Result	✗ Failed
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #14** 2021-07-26 15:12**MOT test number** 900475929766**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2021-07-26 13:58**MOT test number** 408412131291**Result** ✗ Failed**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-10-22 10:34**MOT test number** 283354828296**Result** ✓ Passed**Advice** Undertrays fitted not allowing full inspection of components**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn inner edge and stepping (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge 235/45r17 (5.2.3 (e))

**MOT #11**

2020-10-22 08:20

MOT test number

653173501593

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge bald (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn inner edge and stepping (5.2.3 (e))
- Advice** Undertrays fitted not allowing full inspection of components
- MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge 235/45r17 (5.2.3 (e))
- MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #10

2019-04-23 13:38

MOT test number

718303259967

Result**✓ Passed**

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9

2019-04-15 12:41

MOT test number

710916775883

Result**✗ Failed**

- MAJOR** Offside Front Suspension arm pin or bush excessively worn Rear Bush (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn Rear Bush (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #8** 2018-04-20 08:38**MOT test number** 625151276438**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #7 2017-04-22 09:07**MOT test number** 235454819890**Result** ✓ Passed

- Advice** Rear Tyre worn close to the legal limit both tyres inside edges (4.1.E.1)

MOT #6 2016-04-18 09:11**MOT test number** 357345265769**Result** ✓ Passed**MOT #5** 2015-04-20 14:42**MOT test number** 745940715118**Result** ✓ Passed

**MOT #4**

2015-04-20 09:29

MOT test number

256230215136

Result

✗ Failed

Fail

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail

Offside Front Shock absorber has a serious fluid leak (2.7.3)

MOT #3

2014-04-23 09:14

MOT test number

435513314124

Result

✓ Passed

Notice

Front brake pads wearing low

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #2

2013-04-25 15:28

MOT test number

496695913185

Result

✓ Passed

MOT #1

2013-02-22 16:20

MOT test number

918453853062

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DU1000E
Plate since	2024-03-28
Current registration	 DU1000E
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-02
Last registration	2023-07-26
Complete history	See info



Registration #1	2010-03-02	29 mi
Registration #2	2013-02-22	55.173 mi
Registration #3	2013-04-25	55.939 mi
Registration #4	2014-04-23	69.332 mi
Registration #5	2015-04-20	81.215 mi
Registration #6	2015-04-20	81.215 mi
Registration #7	2016-04-18	92.414 mi
Registration #8	2017-04-22	105.584 mi
Registration #9	2018-04-20	116.312 mi
Registration #10	2019-04-15	124.530 mi
Registration #11	2019-04-15	124.530 mi
Registration #12	2019-04-15	124.530 mi
Registration #13	2019-04-15	124.530 mi
Registration #14	2019-04-15	124.530 mi
Registration #15	2019-04-15	124.530 mi
Registration #16	2019-04-15	124.530 mi
Registration #17	2019-04-15	124.530 mi
Registration #18	2019-04-15	124.530 mi
Registration #19	2019-04-15	124.530 mi
Registration #20	2019-04-15	124.530 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 371263