



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-02
Pictures	0
Listing price	View report

source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-10-30
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	52
Total items failed	23

MOT #18	2023-10-31 08:43
MOT test number	156768244201
Result	✓ Passed
Next expiry date	2024-10-30

MOT #17	2023-10-17 09:09
MOT test number	170900807639

Result	✗ Failed
---------------	----------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Exhaust has a major leak of exhaust gases rear silencer (6.1.2 (a))
- Fail** Offside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2022-10-26 08:50

MOT test number

109704412268

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Inner Suspension arm pin or bush worn but not resulting in excessive movement both rear wishbone bushes (5.3.4 (a) (i))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor

Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #15

2021-11-29 12:09

MOT test number

816413742491

Result

✓ Passed

MOT #14

2020-10-19 15:58

MOT test number

847295178852

Result

✓ Passed

Advice

Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice

Rear Exhaust has a minor leak of exhaust gases rear box (6.1.2 (a))

Advice

Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice

Covers fitted restricting view of some components

Advice

Offside Front Integral body structure is deformed but structural rigidity is not significantly reduced bumper and wing damaged (6.1.1 (a) (i))

**MOT #13**

2020-10-19 12:17

MOT test number

751352927812

Result

✗ Failed

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Nearside Rear Anti-roll bar linkage pin or bush likely to become detached has already become detached (5.3.4 (a) (ii))

Advice Rear Exhaust has a minor leak of exhaust gases rear box (6.1.2 (a))

Advice Covers fitted restricting view of some components

Fail Offside Rear Upper Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Integral body structure is deformed but structural rigidity is not significantly reduced bumper and wing damaged (6.1.1 (a) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12

2019-10-17 14:24

MOT test number

827673353859

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases EXHAUST BOX (6.1.2 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened WORN (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE & CLOSE TO LIMIT (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened WORN (1.1.14 (a) (ii))

**MOT #11**

2019-10-17 09:08

MOT test number

137421228152

Result**✗ Failed****Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt SPLIT (6.1.7 (g) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened WORN (1.1.14 (a) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened WORN (1.1.14 (a) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases EXHAUST BOX (6.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE & CLOSE TO LIMIT (5.2.3 (e))

**MOT #10**

2018-11-12 16:56

MOT test number

381135346165

Result

✓ Passed

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #9

2018-11-12 15:05

MOT test number

841147224537

Result

✗ Failed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #8** 2018-11-08 12:53**MOT test number** 456558721214**Result** ✗ Failed**Advice** Both rear brake pad(s) wearing thin**Advice** Offside front tyre sidewall has slight damage no cords exposed**Minor** Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Engine covers and under trays fitted**Advice** Both front suspension arm pin or bushes worn but not resulting in excessive movement**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside rear tyre inner edge starting to wear slightly**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #7** 2017-10-24 12:56**MOT test number** 470918255661**Result** ✓ Passed**MOT #6** 2017-10-24 12:56**MOT test number** 604168889691**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2016-10-29 08:18**MOT test number** 844061732160**Result** ✓ Passed**Advice** Upper/lower covers fitted restricting view of some testable items

**MOT #4** 2015-10-12 15:03**MOT test number** 659508693186**Result** ✓ Passed**MOT #3** 2015-10-12 09:49**MOT test number** 234658541444**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2014-10-15 09:44**MOT test number** 396748284238**Result** ✓ Passed**MOT #1** 2014-10-14 10:27**MOT test number** 617617484217**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 October 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-10-18
Last registration	2023-10-31
Complete history	See info



Registration #1	2011-10-18	12 mi
Registration #2	2014-10-14	66.753 mi
Registration #3	2014-10-15	66.753 mi
Registration #4	2015-10-12	86.286 mi
Registration #5	2015-10-12	86.286 mi
Registration #6	2016-10-29	97.227 mi
Registration #7	2017-10-24	105.852 mi
Registration #8	2017-10-24	105.852 mi
Registration #9	2018-11-08	117.836 mi
Registration #10	2018-11-12	118.065 mi
Registration #11	2019-10-29	121.277 mi
Registration #12	2019-10-29	121.277 mi
Registration #13	2019-10-29	121.277 mi
Registration #14	2019-10-29	121.277 mi
Registration #15	2019-10-29	121.277 mi
Registration #16	2019-10-29	121.277 mi
Registration #17	2019-10-29	121.277 mi
Registration #18	2019-10-29	121.277 mi
Registration #19	2019-10-29	121.277 mi
Registration #20	2019-10-29	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212