



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Grey
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-02
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	32
Total items failed	6

MOT #17 2024-02-01 15:40

MOT test number 861028363953

Result ✓ Passed

Next expiry date 2025-02-02

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear beam axle has light corrosion

MOT #16 2023-02-03 14:39

MOT test number 950995752896

Result ✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #15**

2023-02-03 10:29

MOT test number

774487547755

Result**✗ Failed**

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #14

2022-01-31 16:22

MOT test number

465875525333

Result**✓ Passed**

- Advice** Both rear shocks and exhaust badly corroded
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13

2020-12-21 14:04

MOT test number

649437989654

Result**✓ Passed**

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #12** 2019-11-29 09:19**MOT test number** 790440204383**Result** ✓ Passed**Advice** Rear Position lamp slightly affected by the operation of another lamp Both position lamps affected by indicators (4.2.3 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both front discs lipped (1.1.14 (a) (ii))**Advice** Offside Rear Wheel arch liner damaged**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #11** 2018-11-30 09:45**MOT test number** 724767420001**Result** ✓ Passed**MOT #10** 2018-11-29 14:29**MOT test number** 910056953646**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2017-11-28 13:21**MOT test number** 564399679482**Result** ✓ Passed**MOT #8** 2017-11-27 15:30**MOT test number** 544713977755**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #7** 2017-05-09 10:56**MOT test number** 301776637165**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-05-13 09:56**MOT test number** 979731542843**Result** ✓ Passed**MOT #5** 2015-05-28 10:57**MOT test number** 947218745113**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nail in offside rear tyre**MOT #4** 2014-05-17 14:05**MOT test number** 529017634160**Result** ✓ Passed**MOT #3** 2013-06-03 17:02**MOT test number** 538434153147**Result** ✓ Passed**Notice** Centre rear seatbelt buckle casing damaged**MOT #2** 2012-12-04 13:59**MOT test number** 125819632384**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-12-04 11:04
MOT test number	407379132428
Result	✗ Failed
Fail	Offside Rear fog lamp insecure (1.3.2a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-20
Last registration	2024-02-01
Complete history	See info



Registration #1	2009-11-20	14 mi
Registration #2	2012-12-04	17.325 mi
Registration #3	2012-12-04	17.325 mi
Registration #4	2013-06-03	17.883 mi
Registration #5	2014-05-17	22.547 mi
Registration #6	2015-05-28	30.102 mi
Registration #7	2016-05-13	38.579 mi
Registration #8	2017-05-09	45.906 mi
Registration #9	2017-11-27	48.482 mi
Registration #10	2017-11-28	48.483 mi
Registration #11	2019-05-20	55.000 mi
Registration #12	2019-05-20	55.000 mi
Registration #13	2019-05-20	55.000 mi
Registration #14	2019-05-20	55.000 mi
Registration #15	2019-05-20	55.000 mi
Registration #16	2019-05-20	55.000 mi
Registration #17	2019-05-20	55.000 mi
Registration #18	2019-05-20	55.000 mi
Registration #19	2019-05-20	55.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694