




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Red
Year of manufacture	2002
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-14
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	18
Total items failed	7

MOT #22 2023-08-22 08:07

MOT test number 615658776131

Result ✓ Passed

Next expiry date 2024-08-31

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Play in steering rack inner joint(s) both
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #21 2022-09-01 13:50

MOT test number 894604697731

Result ✓ Passed

**MOT #20** 2022-09-01 13:50**MOT test number** 311929232374**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #19** 2021-06-28 08:08**MOT test number** 820784006591**Result** ✓ Passed**MOT #18** 2019-05-03 08:58**MOT test number** 763387029506**Result** ✓ Passed**Advice** Play in inner rack ends**MOT #17** 2019-04-19 09:37**MOT test number** 924691754225**Result** ✗ Failed**Fail** Headlamp levelling device inoperative (4.1.5 (a))**Advice** Play in inner rack ends**Fail** Headlamp levelling device cannot be operated from the driver's seat (4.1.5 (b))**MOT #16** 2018-04-30 08:36**MOT test number** 741140238527**Result** ✓ Passed**MOT #15** 2017-06-26 13:51**MOT test number** 869520392516**Result** ✓ Passed

**MOT #14** 2016-09-09 08:30**MOT test number** 395131202819**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #13** 2015-09-18 14:06**MOT test number** 716143864170**Result** ✓ Passed**MOT #12** 2014-09-02 10:24**MOT test number** 838535744272**Result** ✓ Passed**MOT #11** 2013-04-26 16:31**MOT test number** 517656113124**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2013-04-26 15:43**MOT test number** 576236113198**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2012-03-08 10:46**MOT test number** 545698662030**Result** ✓ Passed**MOT #8** 2011-04-05 08:53**MOT test number** 109645691076**Result** ✓ Passed**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #7** 2010-04-08 12:56**MOT test number** 361898090095**Result** ✓ Passed**MOT #6** 2010-04-08 12:31**MOT test number** 644698790027**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #5** 2009-03-14 11:01**MOT test number** 391273879029**Result** ✓ Passed**MOT #4** 2008-03-22 09:26**MOT test number** 840332488068**Result** ✗ Failed**Pass with rectification** Front Headlamp aim too high and too far to the right. (1.8)



MOT #3	2008-03-22 09:26
MOT test number	782222288074
Result	✓ Passed
MOT #2	2007-03-24 09:05
MOT test number	734903887076
Result	✓ Passed
MOT #1	2006-03-25 13:09
MOT test number	374334286062
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BF02DVK
Plate since	2024-03-29
Current registration	 BF02DVK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-03-21
Last registration	2023-08-22
Complete history	See info



Registration #1	2002-03-21	20 mi
Registration #2	2006-03-25	11.341 mi
Registration #3	2007-03-24	15.355 mi
Registration #4	2008-03-22	19.479 mi
Registration #5	2009-03-14	23.648 mi
Registration #6	2010-04-08	26.122 mi
Registration #7	2010-04-08	26.122 mi
Registration #8	2011-04-05	28.025 mi
Registration #9	2012-03-08	32.296 mi
Registration #10	2013-04-26	40.844 mi
Registration #11	2013-04-26	40.844 mi
Registration #12	2014-09-02	47.584 mi
Registration #13	2015-05-20	55.377 mi
Registration #14	2016-05-20	65.377 mi
Registration #15	2017-05-20	75.377 mi
Registration #16	2018-05-20	85.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2020-05-20	105.377 mi
Registration #19	2021-05-20	115.377 mi
Registration #20	2022-05-20	125.377 mi
Registration #21	2023-05-20	135.377 mi
Registration #22	2024-05-20	145.377 mi
Registration #23	2025-05-20	155.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1230 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

Engine number

AZJ 702054