



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV4 VVT-I XT3
Colour	Grey
Year of manufacture	2004
Top speed	112 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	207 g/km
CO2 label	K





MOT history

MOT expiry date 2022-01-11**MOT pass rate** 82 %**MOT passed** 14**Failed MOT tests** 3**Total advice items** 41**Total items failed** 6**MOT #17** 2021-01-12 16:02**MOT test number** 908807017752**Result** ✓ Passed**Next expiry date** 2022-01-11**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-12-02 11:49**MOT test number** 792154672168**Result** ✓ Passed**MOT #15** 2018-11-26 11:45**MOT test number** 119495001949**Result** ✓ Passed**Advice** Wipers slightly poor**Advice** Rear chassis slightly corroded**Advice** Offside rear tie rod slightly twisted**Advice** Brake pipe corroded, covered in grease or other material offside and nearside front to rear (1.1.11 (c))

**MOT #14** 2017-11-23 16:11**MOT test number** 915916795642**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Centre prop bearing worn**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #13** 2016-11-18 09:41**MOT test number** 866080510226**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #12** 2015-11-28 16:14**MOT test number** 201761239397**Result** ✓ Passed**Advice** Items removed from windscreen**Advice** Offside Front Brake hose slightly chafed ABS wire touching (3.6.B.4d)**Advice** Oil leak**Advice** Rear brake pipes corroded**Advice** Nearside Front Brake hose slightly chafed ABS wire touching (3.6.B.4d)**Advice** Offside front tyre perished

**MOT #11**

2015-11-28 10:27

MOT test number

358244187475

Result**✗ Failed****Advice** Nearside Front Brake hose slightly chafed ABS wire touching (3.6.B.4d)**Advice** Oil leak**Fail** Offside Rear Wheel nut(s) missing (4.2.A.1e)**Advice** Rear brake pipes corroded**Advice** Offside Front Brake hose slightly chafed ABS wire touching (3.6.B.4d)**Advice** Offside front tyre perished**Advice** Items removed from windscreen**MOT #10**

2014-11-25 15:53

MOT test number

967849524356

Result**✓ Passed****Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Windscreen has a crack accross the lower part**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #9**

2014-11-24 14:41

MOT test number

719938324316

Result**✗ Failed****Notice** Windscreen has a crack accross the lower part**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Rear Panhard rod attachment bracket/mounting nut missing (2.4.G.1)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #8** 2013-08-02 16:41**MOT test number** 717274413293**Result** ✓ Passed**MOT #7** 2012-11-14 10:39**MOT test number** 556789412357**Result** ✓ Passed**Advice** Nearside Inner Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Inner Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Front discs corroded**MOT #6** 2011-11-03 08:47**MOT test number** 467187101407**Result** ✓ Passed**Notice** N/s/r tyre wearing on outer edge**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2010-11-10 11:05**MOT test number** 694754710320**Result** ✓ Passed**MOT #4** 2009-10-29 12:13**MOT test number** 960192309379**Result** ✓ Passed



MOT #3	2008-10-07 14:41
MOT test number	570511388286
Result	✓ Passed
MOT #2	2007-10-06 09:24
MOT test number	431129777285
Result	✓ Passed
MOT #1	2007-10-05 15:10
MOT test number	741918677271
Result	✗ Failed
Fail	Centre Front registration plate character(s) likely to be misread (6.3.4b)
Fail	Nearside Rear registration plate character(s) likely to be misread (6.3.4b)
Fail	Centre Front registration plate character(s) incorrectly spaced (6.3.4a)
Fail	Nearside Rear registration plate character(s) incorrectly spaced (6.3.4a)



Tax & MOT check

X
Untaxed**Tax expired:**
1 March 2022**X**
MOT**Expired:**
11 January 2022**Tax status**

Expired at 1 March 2022

Days left

791 days too late

MOT expiry date

11 January 2022

Full MOT history[See MOT history](#)

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-09-15
Last registration	2021-01-12
Complete history	See info



Registration #1	2004-09-15	11 mi
Registration #2	2007-10-05	15.662 mi
Registration #3	2007-10-06	15.662 mi
Registration #4	2008-10-07	20.189 mi
Registration #5	2009-10-29	24.402 mi
Registration #6	2010-11-10	28.562 mi
Registration #7	2011-11-03	32.517 mi
Registration #8	2012-11-14	36.334 mi
Registration #9	2013-08-02	37.556 mi
Registration #10	2014-08-20	38.377 mi
Registration #11	2015-08-20	39.200 mi
Registration #12	2016-08-20	40.023 mi
Registration #13	2017-08-20	40.846 mi
Registration #14	2018-08-20	41.669 mi
Registration #15	2019-08-20	42.492 mi
Registration #16	2020-08-20	43.315 mi
Registration #17	2021-08-20	44.138 mi
Registration #18	2022-08-20	44.961 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1695 mm
Length	3805 mm
Wheel base	2280 mm
Kerb weight	1325 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	1AZ1491272