




report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 T8 TWIN ENGINE INSCRIPTION
Colour	Blue
Year of manufacture	2016
Top speed	140 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	315 BHP
Max. torque	400 Nm at 2.200 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	134.5 mpg
CO2 emission	49 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-06
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	17
Total items failed	5

MOT #10	2024-03-07 14:47
MOT test number	413934247816
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

MOT #9	2024-02-27 10:25
MOT test number	702299283815
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2023-02-10 09:25

MOT test number

716952059844

Result

✓ Passed

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2023-02-08 12:02

MOT test number

134605123654

Result

✗ Failed

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6**

2022-02-11 14:47

MOT test number

347579131527

Result

✓ Passed

MOT #5

2021-02-12 17:36

MOT test number

900970834893

Result

✓ Passed

Advice Engine cover fitted and under tray fitted

**MOT #4** 2021-02-12 17:36**MOT test number** 643108260118**Result** ✗ Failed**Advice** Engine cover fitted and under tray fitted**Pass with rectification** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #3** 2020-01-08 16:11**MOT test number** 969009943603**Result** ✓ Passed**MOT #2** 2020-01-08 15:40**MOT test number** 235768108138**Result** ✗ Failed**Fail** Front Headlamp aim too low (4.1.2 (a))**MOT #1** 2018-12-17 12:51**MOT test number** 281671791253**Result** ✓ Passed**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-01-16
Last registration	2024-03-07
Complete history	See info



Registration #1	2016-01-16	11 mi
Registration #2	2018-12-17	40.284 mi
Registration #3	2020-01-08	54.342 mi
Registration #4	2020-01-08	54.342 mi
Registration #5	2020-01-08	54.342 mi
Registration #6	2021-02-12	60.334 mi
Registration #7	2021-02-12	60.334 mi
Registration #8	2021-02-12	60.334 mi
Registration #9	2021-02-12	60.334 mi
Registration #10	2021-02-12	60.334 mi
Registration #11	2021-02-12	60.334 mi
Registration #12	2021-02-12	60.334 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2140 mm
Height	1776 mm
Length	4950 mm
Wheel base	2984 mm
Kerb weight	2318 kg
Max. allowed weight	3010 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1773802