



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	White
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1	
Date	2021-07-24
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	51
Total items failed	0

MOT #13	2023-08-25 10:41
MOT test number	160853539394
Result	✓ Passed
Next expiry date	2024-08-24
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Oil leak, but not excessive gearbox driveshaft oil seal (8.4.1 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #12

2023-08-24 10:20

MOT test number

692625030337

Result

✗ Failed

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Brake fluid close to minimum mark (1.1.10 (d) (ii))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR

Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

DANGEROUS

Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Oil leak, but not excessive gearbox driveshaft oil seal (8.4.1 (a) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #11

2022-07-13 15:11

MOT test number

571352166042

Result

✓ Passed

- Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Nail in tyre
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Tyre slightly damaged outer side wall (5.2.3 (d) (ii))
- Advice

Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #10**

2022-07-11 14:54

MOT test number

134223440793

Result**✗ Failed**

- MAJOR** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Rear Tyre slightly damaged outer side wall (5.2.3 (d) (ii))

MOT #9

2021-07-06 09:30

MOT test number

130391891647

Result**✓ Passed**



MOT #8	2020-07-14 10:27
---------------	------------------

MOT test number	257090918124
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2019-05-01 08:37
---------------	------------------

MOT test number	347001867527
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2018-05-10 16:51
---------------	------------------

MOT test number	337566198565
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2017-05-08 09:47
---------------	------------------

MOT test number	765988152241
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-05-11 11:00
---------------	------------------

MOT test number	774945626523
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-05-06 14:58
---------------	------------------

MOT test number	915876625175
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-12-18 13:41
---------------	------------------

MOT test number	597862054347
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2014-07-22 13:29
MOT test number	785653904296
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	ND11WDG
Plate since	2024-03-29
Current registration	ND11WDG
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-29
Last registration	2023-08-25
Complete history	See info



Registration #1	2011-07-29	20 mi
Registration #2	2014-07-22	18.498 mi
Registration #3	2014-12-18	21.638 mi
Registration #4	2015-05-06	23.713 mi
Registration #5	2016-05-11	34.452 mi
Registration #6	2017-05-08	42.167 mi
Registration #7	2018-05-10	51.687 mi
Registration #8	2019-05-01	60.254 mi
Registration #9	2020-05-01	69.321 mi
Registration #10	2021-05-01	78.388 mi
Registration #11	2022-05-01	87.455 mi
Registration #12	2023-05-01	96.522 mi
Registration #13	2024-05-01	105.589 mi
Registration #14	2025-05-01	114.656 mi
Registration #15	2026-05-01	123.723 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212