





### General information

Make	VOLKSWAGEN
Model	SCIROCCO GT
Colour	Blue
Year of manufacture	2009
Top speed	145 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	200 BHP
Max. torque	280 Nm at 1.700 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I







## Internet history

Entry 1

Date


Pictures

2021-06-20

25

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-25
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #15	2023-06-26 10:10
MOT test number	210699864777
Result	Passed
Next expiry date	2024-06-25
Advice AGE RELATED CORROSSION TO CHASSIS SUSPENSION AND BRAKING PARTS	

MOT #14	2022-05-24 15:27
MOT test number	522716042106
Result	✓ Passed

MOT #13	2022-05-20 15:1	13
MOT test i	number 59185776528	}5
Result	× Faile	ed .
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Front Tyre worn close to legal limit/worn on edge BOTH FRONT TYRES LOW (5.2.3 (e))	
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	

MOT #12	2021-06-09 10:35
MOT test number	698949228375
Result	✓ Passed





MOT #11	2	2021-01-06 14:55
MOT test	number	915736006487
Result		🗸 Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #10		2021-01-06 11:04
MOT test i	number	250418053673
Result		🗙 Failed
Advice	Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	))

MOT #9		2020-01-10 14:59
MOT test	number	781834324862
Result		✓ Passed
Advice	Offside Rear Service brake binding but not excessively slight bind (1.2.1 (f))	
Advice	Nearside Rear Service brake binding but not excessively slight bind (1.2.1 (f))	

MOT #8	2019-01-30 13:04
MOT test number	513719736602
Result	✓ Passed

MOT #7	2018-01-15 10:53
MOT test number	171090679727
Result	✓ Passed





MOT #	6	2017-01-24 09:06
MOT te	est number	369066541457
Result		✓ Passed
MOT #	5	2017-01-18 14:44
MOT te	est number	935383623686
Result		🗙 Failed
Fail	Offside Rear rear brake excessively fluctuating (3.7.B.3)	
Fail	Offside front brake excessively fluctuating (3.7.B.3)	
Fail	Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)	
Fail	Nearside front brake excessively fluctuating (3.7.B.3)	
Fail	Offside rear brake binding (3.7.B.1)	
Advid	Front brake discs corroed	

MOT #4	2016-01-25 12:06
MOT test number	737174371729
Result	✓ Passed
МОТ #3	2015-01-23 11:25
MOT test number	548423725028
Result	✓ Passed
MOT #2	2014-02-01 11:35
MOT test number	655572934048
Result	✓ Passed
	001010110000

MOT #1	2012-10-11 09:29
MOT test number	938365782290
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires:	
1 July 2024 Tax status	Expires: 25 June 2024 Valid until 1 July	
Days left	62	
MOT expiry date	25 June 2024	
Full MOT history	See MOT history	

## Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETTOR
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =





## Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
*********	
**********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Rumber of plates	,
Rumber of plates Carrent registration	
Rumber of plates Carrent registration Fals since	
Rumber of protes Current registration Current registration	
Rumber of plates Carrent registration Fate since Fate since Fate since	1000-20-20





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-30
Last registration	2023-06-26
Complete history	See info



Registration #1	2009-09-30	22 mi
Registration #2	2012-10-11	15.241 mi
Registration #3	2014-02-01	20.543 mi
Registration #4	2015-01-23	29.572 mi
Registration #5	2016-01-25	38.348 mi
Registration #6	2017-01-18	46.329 mi
Registration #7	2017-01-24	46.416 mi
Registration #8	2018-01-15	54.010 mi
Registration #9	2019-01-30	60.327 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





#### Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
S0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1740 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAW 031599