



report date: 2024-03-28

General information

Make	FORD
Model	KA STUDIO
Colour	Silver
Year of manufacture	2008
Top speed	104 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	106 Nm at 3.000 rpm
Engine capacity	1.299 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	31
Total items failed	4

MOT #16 2023-08-09 10:48

MOT test number 790359982693

Result ✓ Passed

Next expiry date 2024-08-08

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive front end of offside sill (5.3.6 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

MOT #15 2022-07-22 07:48

MOT test number 540288660557

Result ✓ Passed

Advice Offside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #14** 2021-08-09 14:27**MOT test number** 791638269483**Result** ✓ Passed

Advice Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive front mounting (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive front mounting (5.3.6 (a) (i))

MOT #13 2020-09-22 11:32**MOT test number** 458920400866**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12 2020-09-22 11:32**MOT test number** 325686706744**Result** ✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2019-09-13 13:13**MOT test number** 971874724180**Result** ✓ Passed

Advice Rear tyres perished

**MOT #10** 2019-09-13 08:39**MOT test number** 651472571602**Result** ✗ Failed**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear tyres perished**Fail** Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**MOT #9** 2018-09-26 15:14**MOT test number** 656810743411**Result** ✓ Passed**MOT #8** 2017-09-13 09:56**MOT test number** 922137073219**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Body has slight corrosion sill (6.1.B.2)**Advice** Offside Rear Body has slight corrosion (6.1.B.2)**Advice** Nearside Front Body has slight corrosion sill (6.1.B.2)**Advice** Offside Rear Body has slight corrosion sill (6.1.B.2)**MOT #7** 2016-09-19 10:11**MOT test number** 862296518236**Result** ✓ Passed**MOT #6** 2015-09-15 11:02**MOT test number** 749589796486**Result** ✓ Passed

**MOT #5** 2014-09-11 16:30**MOT test number** 586594354250**Result** ✓ Passed**Notice** Steering rack leaking and slight play o/s**Advice** Body has slight corrosion (6.1.B.2)**Notice** Front wipers smear**Advice** Rear Body has slight corrosion (6.1.B.2)**MOT #4** 2013-09-11 12:05**MOT test number** 417664253266**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #3** 2012-09-27 11:45**MOT test number** 309991972492**Result** ✓ Passed**MOT #2** 2011-09-30 13:23**MOT test number** 218883071204**Result** ✓ Passed**MOT #1** 2011-09-29 14:23**MOT test number** 226202771210**Result** ✗ Failed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Steering system has excessive free play detected at the steering wheel (steering rack fitted)
(2.2.A.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	AO58HXC
Plate since	2024-03-28
Current registration	AO58HXC
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-30
Last registration	2023-08-09
Complete history	See info



Registration #1	2008-09-30	19 mi
Registration #2	2011-09-29	17.586 mi
Registration #3	2011-09-30	17.586 mi
Registration #4	2012-09-27	22.684 mi
Registration #5	2013-09-11	27.636 mi
Registration #6	2014-09-11	31.788 mi
Registration #7	2015-09-15	35.786 mi
Registration #8	2016-09-19	39.855 mi
Registration #9	2017-09-13	43.971 mi
Registration #10	2018-09-13	48.087 mi
Registration #11	2019-09-13	52.203 mi
Registration #12	2020-09-13	56.319 mi
Registration #13	2021-09-13	60.435 mi
Registration #14	2022-09-13	64.551 mi
Registration #15	2023-08-09	68.667 mi
Registration #16		
Registration #17		
Registration #18		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	887 kg
Max. allowed weight	1265 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	7M75675