





report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO 850 ENTERPRISE L1 BLUEHDI
Colour	White
Year of manufacture	2018
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-07-01

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-23
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	14
Total items failed	4

MOT #6		2024-04-22 08:18
MOT test	number	398148080399
Result		✓ Passed
Next expi	ry date	2025-04-23
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2023-04-12 09:47
MOT test number	593277841275
Result	✓ Passed
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



MOT #4 2023-04-12 08:15

MOT test number 791543163766

Result X Failed

MAJOR Rear Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MAJOR Front Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MAJOR Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

MOT #3 2022-03-24 16:26

MOT test number 618085390169

Result \(\sqrt{Passed} \)

MOT #2 2022-03-24 16:26

MOT test number 850626100802

Result X Failed

Pass with rectification Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4

(b) (ii))

Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

(b) (ii))

MOT #1 2021-03-26 09:42

MOT test number 427007026185

Result

Passed

Minor Drive shaft joint constant velocity boot severely deteriorated outer (6.1.7 (g) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	23 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	*********	
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.		More info >
器 UK	Plate changes	
THE REPORT OF THE PROPERTY OF	See in this check if this CITROEN had different number plates.	
THE REPORT OF THE PROPERTY OF	Number of plates	,
Plate since	Current registration	NK SIZ
Plate since	Plate since	
More info >	Current registration	UK UK
More info >	Plate since	
		More info >

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-04-24
Last registration	2024-04-22
Complete history	See info



Registration #1	2018-04-24	15 mi
Registration #2	2021-03-26	22.114 mi
Registration #3	2022-03-24	35.801 mi
Registration #4	2022-03-24	35.801 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHB3279953

CarCheck.co.uk page 11/11