



report date: 2024-03-28

General information

| | |
|---------------------|--------------------|
| Make | VOLKSWAGEN |
| Model | TOURAN TDI SE 5STR |
| Colour | Grey |
| Year of manufacture | 2008 |
| Top speed | 110 mph |
| 0 - 60 mph | 13.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 103 BHP |
| Max. torque | 250 Nm at 1.900 rpm |
| Engine capacity | 1.896 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 156 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-11 |
| Pictures | 22 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-23 |
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 23 |
| Total items failed | 6 |

| | |
|------------------|---------------------------------------------------------------------------|
| MOT #15 | 2023-07-24 16:21 |
| MOT test number | 771576270769 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-23 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Minor | Nearside Side repeater insecure (4.4.1 (c) (i)) |
| Advice | Nearside Rear Service brake binding but not excessively (1.2.1 (f)) |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Minor | Front Windscreen wiper blade defective both (3.4 (b) (i)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #14**

2023-07-12 09:01

MOT test number

419606967437

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Side repeater insecure (4.4.1 (c) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Front Windscreen wiper blade defective both (3.4 (b) (i))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #13**

2022-07-05 13:25

MOT test number

549627758382

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2022-07-05 08:07

MOT test number

238612327268

Result**✗ Failed****Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-07-07 10:56**MOT test number** 567542444913**Result** ✓ Passed**MOT #10** 2020-07-07 13:20**MOT test number** 350617905961**Result** ✓ Passed**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Front Upper Windscreen damaged but not adversely affecting driver's view slight chip (3.2 (a) (i))**MOT #9** 2019-07-06 07:58**MOT test number** 690093752889**Result** ✓ Passed**MOT #8** 2018-07-09 09:05**MOT test number** 722596319109**Result** ✓ Passed**MOT #7** 2017-07-04 09:36**MOT test number** 672172418396**Result** ✓ Passed**Advice** Offside Front Upper Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Inner Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2016-07-02 11:06**MOT test number** 955300331410**Result** ✓ Passed

**MOT #5** 2015-06-27 11:11**MOT test number** 386438675156**Result** ✓ Passed**MOT #4** 2014-07-05 10:23**MOT test number** 337926184188**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-06-26 11:53**MOT test number** 279867573457**Result** ✓ Passed**MOT #2** 2012-07-11 12:52**MOT test number** 925623392173**Result** ✓ Passed**MOT #1** 2011-06-25 11:27**MOT test number** 536246471183**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
23 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 December |
| Days left | 217 |
| MOT expiry date | 23 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---------------------------------------------------------------------------------------------|
| Number of plates | 1 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2008-07-17 |
| Last registration | 2023-07-24 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-07-17 | 22 mi |
| Registration #2 | 2011-06-25 | 46.596 mi |
| Registration #3 | 2012-07-11 | 54.564 mi |
| Registration #4 | 2013-06-26 | 61.048 mi |
| Registration #5 | 2014-07-05 | 69.093 mi |
| Registration #6 | 2015-06-27 | 74.598 mi |
| Registration #7 | 2016-07-02 | 81.787 mi |
| Registration #8 | 2017-07-04 | 89.068 mi |
| Registration #9 | 2018-07-09 | 95.321 mi |
| Registration #10 | 2019-06-25 | 101.574 mi |
| Registration #11 | 2020-06-25 | 107.827 mi |
| Registration #12 | 2021-06-25 | 114.080 mi |
| Registration #13 | 2022-06-25 | 120.333 mi |
| Registration #14 | 2023-06-25 | 126.586 mi |
| Registration #15 | 2024-06-25 | 132.839 mi |
| Registration #16 | 2025-06-25 | 139.092 mi |
| Registration #17 | 2026-06-25 | 145.345 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2066 mm |
| Height | 1635 mm |
| Length | 4391 mm |
| Wheel base | 2677 mm |
| Kerb weight | 1498 kg |
| Max. allowed weight | 2210 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|-----------------|------------|
| Number of seats | 7 |
| Engine number | BXE A27658 |