



YBIIPKJ

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 280 MWB SHR P/V 85
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-15
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-31
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	72
Total items failed	17

MOT #15	2024-04-01 17:16
MOT test number	783544530209
Result	✓ Passed
Next expiry date	2025-03-31
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Under body corrosion covered on under seal spray.

**MOT #14**

2023-03-30 14:52

MOT test number

825874931607

Result

✓ Passed

- Advice** Nearside Front Inner sill area has hole due to corrosion
- Advice** Oil leak, but not excessive slight (8.4.1 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
- Advice** Underside of vehicle corroded
- Advice** Offside Front Inner sill area has hole due to corrosion
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre

**MOT #13**

2023-03-23 09:22

MOT test number

108659322541

Result**✗ Failed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
- Advice** Underside of vehicle corroded
- Advice** Offside Rear Nail in tyre
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Inner sill area has hole due to corrosion
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Oil leak, but not excessive slight (8.4.1 (a) (i))
- Advice** Nearside Front Inner sill area has hole due to corrosion
- Fail** Offside Rear Leaf spring fractured front shackle (5.3.1 (b) (i))

MOT #12

2022-03-10 14:06

MOT test number

912212393578

Result**✓ Passed**

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #11**

2022-03-10 10:31

MOT test number

455035532772

Result**✗ Failed****Fail** Brake performance not tested (1.2.1 (g))**Fail** Rear Brake pipe excessively damaged (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #10**

2020-12-09 10:40

MOT test number

874369490820

Result**✓ Passed****Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Brake pipe corroded, covered in grease or other material Front to back rear section (1.1.11 (c))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))**Advice** Fluid leak, but not excessive Antifreeze (8.4.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))



MOT #9	2019-06-19 10:41
MOT test number	410076651181
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2019-06-18 14:43
MOT test number	938364112711
Result	✗ Failed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Nail in tyre
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7**

2018-06-27 15:15

MOT test number

810141985801

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #6

2018-06-19 10:12

MOT test number

217745528618

Result

✗ Failed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #5** 2017-06-09 09:41**MOT test number** 364677156186**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2016-06-23 15:11**MOT test number** 765235612069**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2016-06-23 09:10**MOT test number** 154681550337**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Brake pipe excessively corroded front to rear (3.6.B.2c)**MOT #2** 2015-06-24 13:10**MOT test number** 688805975185**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)



MOT #1	2015-06-24 10:24
MOT test number	986315975179
Result	✗ Failed
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Fail	Centre Stop lamp not working (1.2.1b)
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 March 2025

Tax status	Valid until 1 September
-------------------	-------------------------

Days left	124
------------------	-----

MOT expiry date	31 March 2025
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-07-21
Last registration	2024-04-01
Complete history	See info



Registration #1	2011-07-21	15 mi
Registration #2	2015-06-24	76.056 mi
Registration #3	2015-06-24	76.056 mi
Registration #4	2016-06-23	83.701 mi
Registration #5	2016-06-23	83.705 mi
Registration #6	2017-06-09	89.762 mi
Registration #7	2018-06-19	92.193 mi
Registration #8	2018-06-27	92.209 mi
Registration #9	2019-06-18	94.691 mi
Registration #10	2020-06-20	95.277 mi
Registration #11	2020-06-20	95.277 mi
Registration #12	2020-06-20	95.277 mi
Registration #13	2020-06-20	95.277 mi
Registration #14	2020-06-20	95.277 mi
Registration #15	2020-06-20	95.277 mi
Registration #16	2020-06-20	95.277 mi
Registration #17	2020-06-20	95.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	2532 mm
Length	5230 mm
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	BY63554