



HYUNDAI



OU64TU0

report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI GO
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-03
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2024-09-13
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	26
Total items failed	5

MOT #10	2023-09-14 09:30
MOT test number	802065938720
Result	✓ Passed
Next expiry date	2024-09-13

MOT #9	2023-09-13 09:35
MOT test number	440647071887
Result	✗ Failed

- Fail

 Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Pass with rectification

 Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice

 Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

 Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

 Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail

 Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice

 Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2022-09-05 11:59**MOT test number** 226166249475**Result** ✓ Passed**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2021-09-13 08:04**MOT test number** 514171668304**Result** ✓ Passed**MOT #6** 2021-02-25 14:45**MOT test number** 303947262538**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2021-02-25 11:24**MOT test number** 297879406303**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4**

2020-02-07 10:26

MOT test number

762393547082

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3

2020-02-07 10:26

MOT test number

942483239257

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Front Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

2019-02-27 15:18

MOT test number

678878017974

Result

✓ Passed



MOT #1	2017-08-24 09:38
MOT test number	981036815140
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
13 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-13
Last registration	2023-09-14
Complete history	See info



Registration #1	2014-09-13	19 mi
Registration #2	2017-08-24	28.366 mi
Registration #3	2019-02-27	38.438 mi
Registration #4	2020-02-07	43.634 mi
Registration #5	2020-02-07	43.634 mi
Registration #6	2021-02-25	46.927 mi
Registration #7	2022-02-25	50.220 mi
Registration #8	2022-02-25	50.220 mi
Registration #9	2022-02-25	50.220 mi
Registration #10	2022-02-25	50.220 mi
Registration #11	2022-02-25	50.220 mi
Registration #12	2023-09-14	53.513 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4FDEZ280515