





report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L2H2 HDI
Colour	Black
Year of manufacture	2015
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	ı



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-15

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-09-19
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #9		2023-09-15 15:02
MOT test	number	552564163920
Result		✓ Passed
Next expiry date 2024-09-19		
Minor Nearside Front Windscreen damaged but not adversely affecting driver's view scrap arc (3.2 (a) (i))		
Minor	Offside Front Lower Windscreen damaged but not adversely affecting d	lriver's view chip (3.2 (a) (i))

MOT #8	2022-08-24 14:09
MOT test number	200384561807
Result	✓ Passed
MOT #7	2021-09-20 07:39
MOT test number	757856988573
Result	√ Passed

MOT #6	2021-01-11 14:45
MOT test number	629170760718
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number


Result

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Damage to nearside body / panels

Advice Can't see brake pads to advice on (front)

Advice Slight oil leak



CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2019-02-13 11:51

MOT test number 492815173187

Result X Failed

Advice Fuel filter damp

Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Minor Central Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Non obligatory mirror damaged

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #2 2018-02-23 09:12

MOT test number 894452906377

Result / Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

Advice Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

MOT #1 2018-02-22 11:56

MOT test number 879765329930

Result X Failed

Advice Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

Advice Offside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Fail Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords wall (4.1.D.1a)

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 19 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK MIN	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-01-28
Last registration	2023-09-15
Complete history	See info



Registration #1	2015-01-28	27 mi
Registration #2	2018-02-22	67.458 mi
Registration #3	2018-02-23	67.458 mi
Registration #4	2019-02-13	92.305 mi
Registration #5	2019-02-18	92.312 mi
Registration #6	2020-01-22	107.890 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2050 mm
Height	2522 mm
Length	5413 mm
Wheel base	3450 mm
Kerb weight	1925 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	TRJA0810982

CarCheck.co.uk page 12/12