





General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Silver
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg





Internet history

Entry 1

Date

2021-02-03

7

Pictures

Listing price

View report









source: autoonline.co.uk





MOT history

MOT #12	2021-04-06 12:49
MOT test number	723107029700
Result	✓ Passed
Next expiry date	2022-04-05

MOT #11		2021-03-31 10:24
MOT test	number	857887221055
Result		🗙 Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Rear Rear fog lamp adversely affected by the operation of another lam	ıp (4.5.4 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Rear Stop lamp(s) adversely affected by the operation of another lamp	(4.3.3 (b))

MOT #10	2020-07-18 10:19
MOT test number	180185271955
Result	✓ Passed

MOT #9	2020-07-18 08:21	
MOT test number	972659132282	
Result	🗙 Failed	
MAJOR Hazard warning switch inoperative (4.4.2 (a) (ii))		
MAJOR Offside Rear Coil spring insecure (5.3.1 (a) (i))		
DANGEROUS Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))		
MAJOR Nearside Rear Coil spring insecure (5.3.1 (a) (i))		
DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		





MOT #8	2019-04-16 10:47
MOT test number	998799976133
Result	✓ Passed
Advice Child Seat fitted not allowing full inspection of adult belt	
MOT #7	2019-04-16 10:47
MOT test number	208363284327
Result	🗙 Failed
Advice Child Seat fitted not allowing full inspection of adult belt	
Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #6	2018-04-11 10:05
MOT test number	992189510185
Result	✓ Passed

MOT #5	2017-04-25 11:10
MOT test number	585748354874
Result	✓ Passed
Advice Nearside Front Road wheel slightly damaged (4.2.A.1a)	

MOT #4	2017-04-24 13:38
MOT test number	912654932094
Result	🗙 Failed
Advice Nearside Front Road wheel slightly damaged (4.2.A.1a)	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	





MOT #3	2016-08-10 10:16
MOT test number	283922179391
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #2	2016-08-10 10:16
MOT test number	539538786325
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectificationRear fog lamp not working (1.3.2b)	

MOT #1	2016-03-21 17:19
MOT test number	172744743964
Result	✓ Passed





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-05
Last registration	2021-04-06
Complete history	See info



Registration #1	2013-03-05	19 mi
Registration #2	2016-03-21	35.902 mi
Registration #3	2016-08-10	37.286 mi
Registration #4	2016-08-10	37.286 mi
Registration #5	2017-04-24	38.194 mi
Registration #6	2017-04-25	38.194 mi
Registration #7	2018-04-11	42.835 mi
Registration #8		10.319 est
5		
Registration #9		11.777 mi
-		10.000 est
Registration #9		00.000 est 0.000 est 00.000 est
Registration #9 Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11		01.000 est 01.000 est 01.000 est 01.000 est 01.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11