



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D SPORT
Colour	White
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg



LABEL UNKNOWN



MOT history

MOT #15	2021-08-23 11:20
MOT test number	893634101935
Result	✓ Passed
Next expiry date	2022-08-24
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14	2020-08-25 09:24
MOT test number	116274225826
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2020-08-25 09:24
MOT test number	822634362978
Result	✗ Failed
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2019-09-30 11:41
MOT test number	593897050347
Result	✓ Passed

**MOT #11** 2018-09-04 12:45**MOT test number** 134912553364**Result** ✓ Passed

Advice Nearside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2018-08-31 11:37**MOT test number** 729584198760**Result** ✗ Failed

Advice Nearside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Lower Suspension rod pin or bush excessively worn (5.3.4 (a) (i))

MOT #9 2017-08-31 14:24**MOT test number** 851254323753**Result** ✓ Passed**MOT #8** 2016-08-25 16:26**MOT test number** 939334970391**Result** ✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2016-08-25 10:02**MOT test number** 418576844308**Result** ✗ Failed

Fail Nearside Front position lamp(s) incorrect colour (1.1.A.3e)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-08-22 08:17**MOT test number** 961186217515**Result** ✓ Passed**MOT #5** 2015-08-22 08:17**MOT test number** 293805448913**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) incorrect colour (1.1.A.3e)**Pass with rectification** Offside Front position lamp(s) incorrect colour (1.1.A.3e)**MOT #4** 2014-08-28 16:23**MOT test number** 878770244212**Result** ✓ Passed**MOT #3** 2013-08-28 15:24**MOT test number** 389000343259**Result** ✓ Passed**MOT #2** 2012-08-11 12:11**MOT test number** 665534622207**Result** ✓ Passed**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2011-08-19 09:05**MOT test number** 328181431432**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	WJ58OKR
Plate since	2019-03-28
Current registration	WJ58OKR
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-01
Last registration	2021-08-23
Complete history	See info



Registration #1	2008-09-01	10 mi
Registration #2	2011-08-19	29.831 mi
Registration #3	2012-08-11	35.344 mi
Registration #4	2013-08-28	43.266 mi
Registration #5	2014-08-28	49.508 mi
Registration #6	2015-08-22	60.541 mi
Registration #7	2015-08-22	60.541 mi
Registration #8	2016-08-25	69.061 mi
Registration #9	2016-08-25	69.061 mi
Registration #10	2016-08-25	69.061 mi
Registration #11	2016-08-25	69.061 mi
Registration #12	2016-08-25	69.061 mi
Registration #13	2016-08-25	69.061 mi
Registration #14	2016-08-25	69.061 mi
Registration #15	2016-08-25	69.061 mi
Registration #16	2016-08-25	69.061 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	473928
---------------	--------