



report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L3H2 120 LWB HR PV
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2020-08-20
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	37
Total items failed	7

MOT #9	2019-08-19 10:07
MOT test number	211424855459
Result	✓ Passed
Next expiry date	2020-08-20
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Fuel tank slightly damaged
Advice	Anti-lock braking system component slightly damaged (1.6 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2018-08-21 13:12
MOT test number	483273113220
Result	✓ Passed
Advice	Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))

MOT #7	2018-08-21 13:12
MOT test number	381866325675
Result	✗ Failed
Advice	Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))

**MOT #6** 2017-07-20 14:34**MOT test number** 904749172069**Result** ✓ Passed

- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Brake cable has wires broken but is not significantly weakened (3.5.1b)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)

MOT #5 2016-06-04 10:58**MOT test number** 893018450787**Result** ✓ Passed**MOT #4** 2015-06-02 15:07**MOT test number** 525503755113**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Oil leak
- Notice** N/s/f wheel bearing has slight noise
- Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Notice** Spare wheel missing

**MOT #3**

2015-06-02 07:52

MOT test number

559063555115

Result**✗ Failed****Fail** Offside Headlamp aim too low (1.8)**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/f wheel bearing has slight noise**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Spare wheel missing**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #2**

2013-11-19 11:22

MOT test number

406743723365

Result**✓ Passed****Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Noise from gearbox**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Oil leak



MOT #1

2013-11-06 13:43

MOT test number

937430813396

Result

✗ Failed

Fail

Horn not working (1.6.2a)

Notice

Noise from gearbox

Advice

Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Fail

Offside Rear Registration plate lamp not working (1.1.C.1d)

Notice

Oil leak

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-12-01
Last registration	2019-08-19
Complete history	See info



Registration #1	2010-12-01	27 mi
Registration #2	2013-11-06	78.498 mi
Registration #3	2013-11-19	78.498 mi
Registration #4	2015-06-02	103.793 mi
Registration #5	2015-06-02	103.795 mi
Registration #6	2019-08-19	103.797 mi
Registration #7	2019-08-19	103.797 mi
Registration #8	2019-08-19	103.797 mi
Registration #9	2019-08-19	103.797 mi
Registration #10	2019-08-19	103.797 mi

More info >



Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	2015 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ20411973