





report date: 2024-03-28

#### General information

Make	NISSAN
Model	NOTE N-TEC PLUS
Colour	White
Year of manufacture	2013
Top speed	108 mph
0 - 60 mph	10.7 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	110 BHP
Max. torque	153 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history


#### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

# MOT history

MOT expiry date	2025-04-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	23
Total items failed	13

MOT #15		2024-03-26 17:04
MOT test	number	927242974792
Result		<b>✓</b> Passed
Next exp	iry date	2025-04-07
Advice	Front tyre's worn	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice	Exhaust heat shield insecure (centre)	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #14	2024-03-25 16:50
MOT test number	256151557009
Result	<b>X</b> Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Exhaust heat shield insecure (centre)	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Front tyre's worn	

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #13** 2023-04-05 15:39

**MOT test number** 599127510702

**Result** ✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Exhaust system corroded

MOT #12 2023-03-28 11:53

MOT test number 341865503050

Result X Failed

**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Exhaust system corroded

Fail

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #11** 2022-03-30 11:58

**MOT test number** 876531576075

**Result** 
✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Exhaust system corroded

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

**MOT #10** 2021-03-18 15:10

**MOT test number** 656452140276

MOT #9 2021-03-16 17:02

MOT test number 618596999871

**Result** X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2020-04-08 08:49

**MOT test number** 511787463497

**Result** ✓ Passed

MOT #7 2020-04-07 14:07

**MOT test number** 361952314332

**Result** ★ Failed

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #6 2019-08-14 10:44

MOT test number 495156402206

**Result** 
✓ Passed

**Advice** Items removed from driver's view prior to test

CarCheck.co.uk page 5/13



MOT #5

NA13DNU

report date: 2024-03-28

2018-07-11 14:53

MOT test number 617890195192

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2017-07-25 09:41

MOT test number 106441399212

**Result** ✓ Passed

MOT #3 2016-08-04 10:13

**MOT test number** 184178132524

**Result** ✓ Passed

MOT #2 2016-08-04 10:13

MOT test number 522825253420

**Result** X Failed

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

MOT #1 2016-01-19 09:18

MOT test number 654915058355

Result \rightarrow Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	7 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



door of plates

faste since

NA13DNU

report date: 2024-03-28

# For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this NISSAN had different number plates.

ŪK \_\_\_\_\_

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

page 11/13

#### Finance check

CarCheck.co.uk

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-04-15
Last registration	2024-03-26
Complete history	See info



Registration #1	2013-04-15	14 mi
Registration #2	2016-01-19	21.334 mi
Registration #3	2016-08-04	24.003 mi
Registration #4	2016-08-04	24.003 mi
Registration #5	2017-07-25	28.741 mi
Registration #6	2018-07-11	36.486 mi
Registration #7	2019-08-14	48.803 mi
Registration #8	2020-04-07	57.059 mi
Registration #9	2020-04-08	57.059 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1690 mm
Height	1550 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1131 kg
Max. allowed weight	1580 kg

# Additional information

Fuel tank capacity	46 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2
Engine number 46240C