



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	AMICA CDX
Colour	Red
Year of manufacture	2007
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-29
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-04-24
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	11
Total items failed	8

MOT #18	2023-04-25 09:30
MOT test number	646837424619
Result	✓ Passed
Next expiry date	2024-04-24
Advice	Offside Rear Nail in tyre

MOT #17	2022-02-04 09:20
MOT test number	349288509307
Result	✓ Passed

MOT #16	2022-01-28 16:58
MOT test number	222371718122
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner and outer sill (5.3.6 (a) (i))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #15** 2021-07-30 10:40**MOT test number** 254861000798**Result** ✓ Passed

Advice Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security near axle mount (6.2.2 (d) (i))

MOT #14 2021-07-19 11:28**MOT test number** 522009902373**Result** ✗ Failed

Advice Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security near axle mount (6.2.2 (d) (i))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Fail Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting near axle mount (6.2.2 (d) (i))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #13 2020-07-20 14:36**MOT test number** 402915475562**Result** ✓ Passed**MOT #12** 2019-07-15 15:28**MOT test number** 825992146833**Result** ✓ Passed

Advice Brake pipe corroded, covered in grease or other material all pipes greased (1.1.11 (c))

MOT #11 2018-07-16 10:37**MOT test number** 565481961942**Result** ✓ Passed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake pipe corroded, covered in grease or other material all pipes greased (1.1.11 (c))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2017-07-14 12:10**MOT test number** 514649738843**Result** ✓ Passed**Advice** All brake pipes are greased**MOT #9** 2016-07-13 11:15**MOT test number** 134463312533**Result** ✓ Passed**MOT #8** 2015-08-28 11:05**MOT test number** 984862541119**Result** ✓ Passed**MOT #7** 2014-07-02 14:44**MOT test number** 266383284422**Result** ✓ Passed**MOT #6** 2013-06-20 16:13**MOT test number** 715371373115**Result** ✓ Passed**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #5** 2012-06-12 16:03**MOT test number** 275024362140**Result** ✓ Passed**MOT #4** 2011-06-23 11:32**MOT test number** 358714371100**Result** ✓ Passed



MOT #3	2011-03-14 11:10
MOT test number	928833571086
Result	✓ Passed

MOT #2	2011-03-14 11:10
MOT test number	376103171049
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #1	2010-03-02 09:24
MOT test number	182931060017
Result	✓ Passed
<div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✗
MOT
Expired:
24 April 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	24 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-03
Last registration	2023-04-25
Complete history	See info



Registration #1	2007-03-03	6 mi
Registration #2	2010-03-02	18.647 mi
Registration #3	2011-03-14	24.433 mi
Registration #4	2011-06-23	25.940 mi
Registration #5	2012-06-12	30.989 mi
Registration #6	2013-06-20	35.062 mi
Registration #7	2014-07-02	38.445 mi
Registration #8	2015-08-28	40.700 mi
Registration #9	2016-07-13	40.961 mi
Registration #10	2017-07-14	42.201 mi
Registration #11	2018-06-20	43.557 mi
Registration #12	2019-06-20	45.017 mi
Registration #13	2020-06-20	46.577 mi
Registration #14	2021-06-20	48.137 mi
Registration #15	2022-06-20	49.697 mi
Registration #16	2023-06-20	51.257 mi
Registration #17	2024-06-20	52.817 mi
Registration #18	2025-06-20	54.377 mi
Registration #19	2026-06-20	55.937 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	932 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2

Engine number

G4HG7M052463