





# General information

| Make                | HYUNDAI        |
|---------------------|----------------|
| Model               | I10 GO SE      |
| Colour              | Blue           |
| Year of manufacture | 2018           |
| Top speed           | 97 mph         |
| Gearbox             | 5 speed Manual |

# Engine & fuel consumption

| Power                   | 65 BHP             |
|-------------------------|--------------------|
| Max. torque             | 95 Nm at 3.500 rpm |
| Engine capacity         | 998 cc             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 42.8 mpg           |
| Consumption extra urban | 65.7 mpg           |
| Consumption combined    | 50.4 mpg           |
| CO2 emission            | 117 g/km           |
| CO2 label               | С                  |





# Internet history

Entry 1

Date

Pictures

2022-08-03

12

Listing price

View report









source: cargurus.co.uk



# MOT history

| MOT expiry date    | 2024-09-04 |
|--------------------|------------|
| MOT pass rate      | 60 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 2          |
| Total advice items | 5          |
| Total items failed | 7          |

| MOT #5           | 2023-08-24 16:43 |
|------------------|------------------|
| MOT test number  | 211452120314     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-09-04       |

| <b>MOT #4</b> 2                                                                              | 023-08-24 12:34 |
|----------------------------------------------------------------------------------------------|-----------------|
| MOT test number                                                                              | 133536100424    |
| Result                                                                                       | 🗙 Failed        |
| Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))                            |                 |
| <b>Fail</b> Offside Rear Service brake excessively binding (1.2.1 (f))                       |                 |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |                 |
| Fail Nearside Front Service brake excessively binding (1.2.1 (f))                            |                 |
| Fail Nearside Rear Service brake excessively binding (1.2.1 (f))                             |                 |
| Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))                            |                 |
| Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))                             |                 |
| <b>Fail</b> Offside Front Service brake excessively binding (1.2.1 (f))                      |                 |

| МОТ #3          | 2022-09-05 15:01 |
|-----------------|------------------|
| MOT test number | 337047923620     |
| Result          | ✓ Passed         |



**WN68VCP** report date: 2024-03-29

| MOT #2                                                                              | 2021-10-16 10:38 |
|-------------------------------------------------------------------------------------|------------------|
| MOT test number                                                                     | 200285406610     |
| Result                                                                              | ✓ Passed         |
|                                                                                     |                  |
| MOT #1                                                                              | 2021-10-16 08:18 |
| MOT test number                                                                     | 843567492578     |
| Result                                                                              | 🗙 Failed         |
| Advice Offside Front Tyre worn close to legal limit/worn on edge Bald on inner edge | e (5.2.3 (e))    |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))         |                  |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))        |                  |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))        |                  |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 March 2025 | ✓<br>MOT<br>Expires:<br>4 September 2024 |
|----------------------------------------|------------------------------------------|
| Tax status                             | Valid until 1 March                      |
| Days left                              | 305                                      |
| MOT expiry date                        | 4 September 2024                         |
| Full MOT history                       | See MOT history                          |

# Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | G          |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |                                        |
|----------|----------------------------------------|
| Date     | FEIDO                                  |
| Category | Lamp                                   |
| Туре     |                                        |
| Damage 2 | VAMPL                                  |
| Date     | ······································ |
| Category | AMP                                    |
| Туре     |                                        |

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.00.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second |             |
|----------------------------------------------------------------------------------------------------------------|-------------|
| **********                                                                                                     |             |
|                                                                                                                |             |
| ******                                                                                                         |             |
| ********                                                                                                       |             |
| ********                                                                                                       |             |
|                                                                                                                | More info > |
| Plate changes                                                                                                  |             |
| See in this check if this HYUNDAI had different number plates.                                                 |             |
| Number of plates                                                                                               |             |
| Current registration                                                                                           |             |
| Plate since                                                                                                    |             |
| Current registration                                                                                           |             |
| Rate sizes                                                                                                     |             |





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2018-10-20 |
| Last registration          | 2023-08-24 |
| Complete history           | See info   |



| Registration #1 | 2018-10-20 | 19 mi      |
|-----------------|------------|------------|
| Registration #2 | 2021-10-16 | 30.620 mi  |
| Registration #3 | 2021-10-16 | 30.620 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 |            | 11.777 est |
| Registration #6 |            | 11.777 esi |
| Registration #7 |            | 11.777 mi  |

More info >





# Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 0567  |                  |
| 0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 79%             |
| Children       | 80%             |
| Pedestrian     | 71%             |
| Safety systems | 56%             |
| Overall rating | 73%             |
| Video          | see crash video |



| Dimensions & weight               |                       |
|-----------------------------------|-----------------------|
| Width                             | 1660 mm               |
| Height                            | 1500 mm               |
| Length                            | 3665 mm               |
| Wheel base                        | 2385 mm               |
| Kerb weight                       | 933 kg                |
| Max. allowed weight               | 1420 kg               |
| Additional information            |                       |
| Fuel tank capacity                | 40                    |
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11          |

| Number of axles | 2            |
|-----------------|--------------|
| Engine number   | G3LAJD120271 |