





General information

Make	BMW
Model	640 640D M SPORT GRAN COUPE
Colour	Silver
Year of manufacture	2014
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry 1

Date Pictures 2021-11-20

39

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	3

МОТ #9	2023-10-16 15:11
MOT test number	657369484167
Result	Passed
Next expiry date	2024-10-18
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

MOT #8 2023-10-13 14:43 586049043296 **MOT test number** Result **X** Failed Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))





MOT #7		2022-10-17 09:19
MOT test	number	743845507744
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

МОТ #6	2021-10-19 07:30
MOT test number	818773604149
Result	✓ Passed

MOT #5	2020-09-28 15:29
MOT test number	479669258435
Result	✓ Passed

MOT #4	1	2020-09-25 09:07
MOT te	st number	222522953563
Result		🗙 Failed
Fail	Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail (d) (ii))Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3		s structure (5.2.3

MOT #3	2019-09-27 14:26
MOT test number	822539005624
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2018-09-28 08:38
MOT test number	817564193871
Result	✓ Passed





MOT #1	2017-09-29 08:17
MOT test number	364800992665
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 18 October 2024
Tax status	Valid until 1 November
Days left	187
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	\$
Category	amp
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-30
Last registration	2023-10-16
Complete history	See info



Registration #1	2014-09-30	7 mi
Registration #2	2017-09-29	48.952 mi
Registration #3	2018-09-28	67.728 mi
Registration #4	2019-09-27	85.585 mi
Registration #5	2020-09-25	95.746 mi
Registration #6	2020-09-28	95.754 mi
Registration #7		11.222 mi
Registration #8		11.222 est
Registration #9		11.222 est
Registration #10		11.222 est
Registration #11		11.227 mi





Car features

S0225	Air conditionin
\$0295	
50482	
50501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	1894 mm
Height	1392 mm
Length	5007 mm
Wheel base	2968 mm
Kerb weight	1790 kg
Max. allowed weight	2410 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	35438970