




report date: 2024-03-29

General information

| | |
|---------------------|---------------------|
| Make | FORD |
| Model | S-MAX TITANIUM TDCI |
| Colour | Blue |
| Year of manufacture | 2007 |
| Top speed | 117 mph |
| 0 - 60 mph | 11.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 130 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 28.5 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 38.7 mpg |
| CO2 emission | 193 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-15 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-28 |
| MOT pass rate | 68 % |
| MOT passed | 15 |
| Failed MOT tests | 7 |
| Total advice items | 64 |
| Total items failed | 12 |

MOT #22 2024-04-22 11:12

MOT test number 207635305641

Result ✓ Passed

Next expiry date 2025-04-28

Advice Exhaust back box hanger broke

Advice Exhaust flex slight blow

Advice Rear suspension arms corroded

MOT #21 2023-04-29 13:18

MOT test number 179084908987

Result ✓ Passed

MOT #20 2022-03-17 15:50

MOT test number 259599076851

Result ✓ Passed

Advice Offside Rear Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #19 2021-09-02 12:14

MOT test number 870222068148

Result ✓ Passed

**MOT #18** 2021-06-16 07:36**MOT test number** 713510364181**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #17** 2020-12-15 14:16**MOT test number** 261352078169**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-12-20 16:27**MOT test number** 762212695624**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material all pipes (1.1.11 (c))**MOT #15** 2019-12-20 11:38**MOT test number** 417490638695**Result** ✗ Failed**Advice** Brake pipe corroded, covered in grease or other material all pipes (1.1.11 (c))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Rear Brake disc significantly and obviously worn inner surface scored (1.1.14 (a) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #14**

2018-12-21 16:50

MOT test number

298582420998

Result

✓ Passed

- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Factory covers fitted obscuring testable items
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Items removed from driver's view prior to test
- Advice** Brake pipe corroded, covered in grease or other material covered in grease (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #13

2018-01-24 17:43

MOT test number

288895562362

| Result | | ✓ Passed |
|--------|--|----------|
| Advice | Brake pipes greased | |
| Advice | Rear Sub-frame corroded but not seriously weakened (2.4.G.1) | |
| Advice | Offside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1) | |
| Advice | Nearside Rear coil spring corroded (2.4.C.1b) | |
| Advice | Nearside Rear tyre heavily cracked 215/60/16 95V | |
| Advice | Rear registration plate delaminated but not likely to be misread (6.3.1d) | |
| Advice | Factory covers fitted obscuring testable items | |
| Advice | Nearside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1) | |
| Advice | Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1) | |
| Advice | Offside Rear coil spring corroded (2.4.C.1b) | |
| Advice | Warning light indicates a service is due | |
| Advice | Items removed from driver's view prior to test | |

**MOT #12**

2018-01-24 17:43

MOT test number

470713354273

Result**✗ Failed**

- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Rear tyre heavily cracked 215/60/16 95V
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Factory covers fitted obscuring testable items
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Warning light indicates a service is due
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Brake pipes greased
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Items removed from driver's view prior to test
- Pass with rectification** Nearside Front Headlamp aim too high (1.8)

MOT #11

2017-01-18 12:37

MOT test number

694422288054

Result**✓ Passed**

- Advice** Engine Cover and Under Tray Fitted
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt O/S and N/S
- Advice** Rear Exhaust Tailpipe Bracket Broken
- Advice** Front Brake Discs Becoming Worn and Lipped

**MOT #10**

2017-01-18 12:21

MOT test number

941871689249

Result**✗ Failed****Fail** Nearside Rear Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Advice** Engine Cover and Under Tray Fitted**Advice** Front Brake Discs Becoming Worn and Lipped**Advice** Rear Child Seat fitted not allowing full inspection of adult belt O/S and N/S**Advice** Rear Exhaust Tailpipe Bracket Broken**MOT #9**

2016-01-26 14:52

MOT test number

598363944076

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened discs (3.5.1i)**MOT #8**

2015-07-16 12:19

MOT test number

126187995154

Result**✓ Passed****MOT #7**

2015-07-08 09:45

MOT test number

117239485174

Result**✗ Failed****Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Offside Rear Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #6** 2014-07-16 09:02**MOT test number** 767037294199**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-08-19 13:15**MOT test number** 756551633225**Result** ✓ Passed**MOT #4** 2012-08-23 14:25**MOT test number** 176476032246**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-08-23 09:54**MOT test number** 735596832260**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #2** 2011-02-04 13:23**MOT test number** 106245931405**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Emissions to clean for a reading



| | |
|-----------------|--|
| MOT #1 | 2011-02-04 08:59 |
| MOT test number | 779765931020 |
| Result | ✗ Failed |
| Fail | Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Notice | Emissions to clean for a reading |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
28 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 28 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2007-12-31 |
| Last registration | 2024-04-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-12-31 | 21 mi |
| Registration #2 | 2011-02-04 | 28.405 mi |
| Registration #3 | 2011-02-04 | 28.405 mi |
| Registration #4 | 2012-08-23 | 41.776 mi |
| Registration #5 | 2012-08-23 | 41.776 mi |
| Registration #6 | 2013-08-19 | 51.653 mi |
| Registration #7 | 2014-07-16 | 61.995 mi |
| Registration #8 | 2015-07-08 | 73.126 mi |
| Registration #9 | 2015-07-16 | 73.238 mi |
| Registration #10 | 2016-01-26 | 78.296 mi |
| Registration #11 | 2017-01-18 | 86.532 mi |
| Registration #12 | 2017-01-18 | 86.532 mi |
| Registration #13 | 2019-05-20 | 95.377 mi |
| Registration #14 | 2019-05-20 | 95.377 mi |
| Registration #15 | 2019-05-20 | 95.377 mi |
| Registration #16 | 2019-05-20 | 95.377 mi |
| Registration #17 | 2019-05-20 | 95.377 mi |
| Registration #18 | 2019-05-20 | 95.377 mi |
| Registration #19 | 2019-05-20 | 95.377 mi |
| Registration #20 | 2019-05-20 | 95.377 mi |
| Registration #21 | 2019-05-20 | 95.377 mi |
| Registration #22 | 2019-05-20 | 95.377 mi |
| Registration #23 | 2019-05-20 | 95.377 mi |
| Registration #24 | 2019-05-20 | 95.377 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2154 mm |
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1905 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 7T72261 |