



report date: 2024-03-29

General information

| | |
|---------------------|----------------------|
| Make | VOLVO |
| Model | V70 D DRIVE R-DESIGN |
| Colour | Blue |
| Year of manufacture | 2010 |
| Top speed | 118 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 109 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 119 g/km |
| CO2 label | C |





Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2021-07-07 |
| Pictures | 44 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-06 |
| Pictures | 42 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-07 |
| MOT pass rate | 71 % |
| MOT passed | 10 |
| Failed MOT tests | 4 |
| Total advice items | 17 |
| Total items failed | 10 |

MOT #14 2024-02-08 08:04

MOT test number 508632792257

Result ✓ Passed

Next expiry date 2025-02-07

Advice Under trays fitted

Advice Rear Exhaust mounting defective (6.1.2 (a))

MOT #13 2023-01-13 12:43

MOT test number 608406446059

Result ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2022-01-27 10:28

MOT test number 146327270765

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement both side trailing arms (5.3.4 (a) (i))

**MOT #11**

2022-01-25 10:44

MOT test number

205621513401

Result

✗ Failed

Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear All direction indicators incorrect colour (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both side trailing arms (5.3.4 (a) (i))**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Headlamps matched pair incorrect colour (4.1.4 (a))**Fail** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #10**

2021-01-04 12:02

MOT test number

837646743424

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9**

2019-07-23 12:55

MOT test number

334986650684

Result

✓ Passed

MOT #8

2019-07-23 08:19

MOT test number

954012097393

Result

✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #7** 2018-07-23 11:09**MOT test number** 556698642155**Result** ✓ Passed**MOT #6** 2018-07-23 11:09**MOT test number** 525807307179**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**MOT #5** 2017-07-21 09:37**MOT test number** 852754550319**Result** ✓ Passed**MOT #4** 2016-07-25 08:53**MOT test number** 252234102506**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** 205 / 60 /16**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-04-14 10:32**MOT test number** 127254805172**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #2 | 2013-12-06 09:48 |
| MOT test number | 539690143305 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2013-12-06 09:48 |
| MOT test number | 936800743309 |
| Result | ✗ Failed |

Pass with rectification

 Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
7 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 7 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2010-12-30 |
| Last registration | 2024-02-08 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-12-30 | 11 mi |
| Registration #2 | 2013-12-06 | 63.697 mi |
| Registration #3 | 2015-04-14 | 81.025 mi |
| Registration #4 | 2016-07-25 | 94.961 mi |
| Registration #5 | 2017-07-21 | 105.316 mi |
| Registration #6 | 2018-07-23 | 114.637 mi |
| Registration #7 | 2018-07-23 | 114.637 mi |
| Registration #8 | 2019-07-23 | 123.054 mi |
| Registration #9 | 2020-05-20 | 131.377 mi |
| Registration #10 | 2021-05-20 | 139.700 mi |
| Registration #11 | 2022-05-20 | 148.023 mi |
| Registration #12 | 2023-05-20 | 156.346 mi |
| Registration #13 | 2024-02-08 | 164.669 mi |
| Registration #14 | 2024-02-08 | 172.992 mi |
| Registration #15 | 2024-02-08 | 181.315 mi |
| Registration #16 | 2024-02-08 | 189.638 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1457 mm |
| Length | 4522 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1442 kg |
| Max. allowed weight | 1900 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------|
| Number of axles | 2 |
| Engine number | 957553 |