



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ-L
Colour	White
Year of manufacture	2010
Top speed	96 mph
Gearbox	5 speed MANUAL

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history


Entry 2

Date	2021-02-04
Pictures	0
Listing price	View report

source: autoonline.co.uk

Entry 1

Date	2021-01-21
Pictures	15
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-08-23
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	5

MOT #13	2023-08-18 16:06
MOT test number	482239669669
Result	✓ Passed
Next expiry date	2024-08-23

MOT #12	2023-08-18 09:04
MOT test number	960873406025
Result	✗ Failed
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Side repeater light intensity significantly reduced (4.4.3 (a))

MOT #11	2022-08-16 11:36
MOT test number	770923082552
Result	✓ Passed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #10**

2022-08-15 08:05

MOT test number

827722756408

Result**✗ Failed****Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))**MOT #9**

2021-08-24 16:00

MOT test number

774849947751

Result**✓ Passed****Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #8**

2021-08-13 13:29

MOT test number

406729757058

Result**✗ Failed****Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Front Exhaust has a major leak of exhaust gases exhaust manifold (6.1.2 (a))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))

**MOT #7** 2020-08-17 09:18**MOT test number** 111100291046**Result** ✓ Passed**MOT #6** 2019-04-12 07:26**MOT test number** 947757143902**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #5** 2018-05-09 08:03**MOT test number** 322480544064**Result** ✓ Passed**Advice** Headlamp bulbs slightly discoloured**Advice** Front tyres perished**Advice** Horn output noise slightly muffled**Advice** Some insecurity of battery**Advice** Rear tyres slightly perished**Advice** Handbrake travel lever travel on limit**MOT #4** 2017-03-31 08:41**MOT test number** 159560064330**Result** ✓ Passed**MOT #3** 2016-04-05 07:56**MOT test number** 684349411370**Result** ✓ Passed



MOT #2	2015-04-04 16:06
MOT test number	447494695026
Result	✓ Passed

MOT #1	2014-08-18 11:45
MOT test number	409620134212
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-14
Last registration	2023-08-18
Complete history	See info



Registration #1	2010-09-14	11 mi
Registration #2	2014-08-18	28.468 mi
Registration #3	2015-04-04	33.696 mi
Registration #4	2016-04-05	36.020 mi
Registration #5	2017-03-31	41.217 mi
Registration #6	2018-05-09	42.816 mi
Registration #7	2019-04-12	50.160 mi
Registration #8	2020-08-17	61.008 mi
Registration #9	2020-08-17	61.008 mi
Registration #10	2020-08-17	61.008 mi
Registration #11	2020-08-17	61.008 mi
Registration #12	2020-08-17	61.008 mi
Registration #13	2020-08-17	61.008 mi
Registration #14	2020-08-17	61.008 mi
Registration #15	2020-08-17	61.008 mi
Registration #16	2020-08-17	61.008 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1131547