



0U1199

report date: 2024-03-28

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	White
Year of manufacture	2011
Top speed	135 mph
0 - 100 km/h	7.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	180 kW / 245 HP / 240 BHP
Max. torque	550 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	42.2 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J





MOT history

MOT expiry date	2024-07-31
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	26
Total items failed	4

MOT #11 2023-07-19 08:18

MOT test number 907208586616

Result ✓ Passed

Next expiry date 2024-07-31

Advice Offside Front Brake pipe corroded, covered in grease or other material Caliper joining pipe (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material caliper joining pipe (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice General corrosion

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10 2022-08-01 12:56

MOT test number 202419990822

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))

Advice Rear Tyre has a cut but not deep enough to reach the ply or cords both (5.2.3 (d) (i))

**MOT #9** 2022-07-28 09:26**MOT test number** 680017924210**Result** ✗ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))

Advice Rear Tyre has a cut but not deep enough to reach the ply or cords both (5.2.3 (d) (i))

Fail Steering rack insecure to the extent there is excessive movement at the mountings (2.1.3 (a) (ii))

MOT #8 2021-07-30 16:36**MOT test number** 866722449084**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2020-10-05 09:38**MOT test number** 673261592913**Result** ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6**

2020-09-23 15:31

MOT test number

776649408614

Result**✗ Failed**

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Rear Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5

2019-05-01 14:12

MOT test number

813392644716

Result**✓ Passed****MOT #4**

2018-03-21 16:34

MOT test number

736380820704

Result**✓ Passed****MOT #3**

2017-01-05 16:11

MOT test number

163644866877

Result**✓ Passed**



MOT #2	2015-06-10 14:13
MOT test number	689051365115
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2014-07-29 12:25
MOT test number	318200114217
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-06-10
Last registration	2023-07-19
Complete history	See info



Registration #1	2011-06-10	12 mi
Registration #2	2014-07-29	23.071 mi
Registration #3	2015-06-10	29.358 mi
Registration #4	2017-01-05	44.547 mi
Registration #5	2018-03-21	55.038 mi
Registration #6	2019-05-01	70.048 mi
Registration #7	2020-05-20	85.058 mi
Registration #8	2021-05-20	100.068 mi
Registration #9	2022-05-20	115.078 mi
Registration #10	2023-05-20	130.088 mi
Registration #11	2024-05-20	145.098 mi
Registration #12	2025-05-20	160.108 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	2177 mm
Height	1737 mm
Length	5089 mm
Wheel base	3002 mm
Kerb weight	2270 kg
Max. allowed weight	3125 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	CJG 015991