

Ford



General information

Make	FORD
Model	C-MAX ZETEC
Colour	White
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	11.5 seconds
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 104 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry	1
Date	

Pictures


2021-08-22


22

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	25
Total items failed	3

MOT #11	2023-09-07 10:42
MOT test number	649606645509
Result	Passed
Next expiry date	2024-09-06
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice O/s/r inner tail lamp damaged	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



DK13UBD
report date: 2024-03-29

MOT #10	2022-07-06 15:3
MOT test	number 83969272162
Result	✓ Passe
Advice	Coolant residue around water pump area
Advice (5.2.3 (e))	Offside Rear Tyre worn close to legal limit/worn on edge 3mm, worn on inner edge & perished
Advice	Coolant level low
Advice	Brake disc worn, but not excessively Both front (1.1.14 (a) (i))
Advice	Offside Rear Inner Light unit damaged
Advice (e))	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm, worn on edges & perished (5.2.3
Advice	Nearside Rear Nail in tyre
Advice	Engine oil level on min

MOT #9	2021-06-25 08:32
MOT test number	850938161043
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2020-06-23 14:53
MOT test number	684899322526
Result	✓ Passed



MOT #7	2020-06-22 08:19
MOT test number	508191013668
Result	🗙 Failed
MAJOR Windscreen washer not working (3.5 (a))	
DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #6	2019-06-25 14:39
MOT test number	822286145491
Result	✓ Passed

MOT #5		2018-06-11 15:23
MOT test	number	287195173685
Result		✓ Passed
Advice	Play in steering rack inner joint(s)	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #42017-05-30 12:01MOT test number869602705610ResultPassedAdviceFront Brake pad(s) wearing thin (3.5.1g)AdviceEngine and under covers fittedAdviceRear Brake pad(s) wearing thin (3.5.1g)

МОТ #3	2016-06-03 06:39
MOT test number	812327075872
Result	✓ Passed

DK13UBD report date: 2024-03-29



DK13UBD report date: 2024-03-29

MOT #2	2016-06-03 06:39	
MOT test number	902247080446	
Result	× Failed	
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Pass with rectification	Windscreen washer provides insufficient washer liquid missing screen (8.2.3)	

MOT #1		2016-01-25 10:38
MOT test	number	618369244814
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit 1.8mm (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit 1.8mm (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	MOT Expires: 6 September 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-22
Last registration	2023-09-07
Complete history	See info



Registration #1	2013-03-22	16 mi
Registration #2	2016-01-25	21.725 mi
Registration #3	2016-06-03	24.107 mi
Registration #4	2016-06-03	24.107 mi
Registration #5	2017-05-30	33.371 mi
Registration #6	2018-06-11	45.474 mi
Registration #7	2019-06-25	56.419 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
\$0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	2067 mm
Height	1626 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1274 kg
Max. allowed weight	1860 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 13/13