



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Blue
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-14
Pictures	50
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-04
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	12
Total items failed	6

MOT #16	2023-07-05 10:11
MOT test number	585314304959
Result	✓ Passed
Next expiry date	2024-07-04

MOT #15	2022-06-28 10:59
MOT test number	465219097393
Result	✓ Passed

MOT #14	2021-07-01 12:50
MOT test number	259121243885
Result	✓ Passed

MOT #13	2020-11-26 09:12
MOT test number	868502173211
Result	✓ Passed

MOT #12	2019-12-03 12:39
MOT test number	454551199393
Result	✓ Passed

**MOT #11** 2018-11-21 12:02**MOT test number** 596495134044**Result** ✓ Passed**MOT #10** 2018-11-20 10:44**MOT test number** 615304660834**Result** ✗ Failed**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9** 2017-12-12 15:40**MOT test number** 619468069025**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged**MOT #8** 2017-12-11 10:43**MOT test number** 397221504588**Result** ✗ Failed**Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)**Fail** Offside Headlamp aim too low (1.8)**Advice** Nearside Non obligatory mirror damaged**Fail** Offside Steering rack gaiter insecure (2.2.D.2d)**MOT #7** 2016-11-30 10:12**MOT test number** 666671980425**Result** ✓ Passed

**MOT #6** 2015-11-06 12:27**MOT test number** 661563518492**Result** ✓ Passed**MOT #5** 2014-11-25 10:31**MOT test number** 537719124313**Result** ✓ Passed**MOT #4** 2013-12-04 10:08**MOT test number** 287478133328**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2012-11-05 10:04**MOT test number** 735200512340**Result** ✓ Passed



MOT #2	2011-11-23 10:44
MOT test number	529307721350
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-11-08 10:06
MOT test number	502212210359
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
4 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-12-04
Last registration	2023-07-05
Complete history	See info



Registration #1	2007-12-04	6 mi
Registration #2	2010-11-08	321.037 mi
Registration #3	2011-11-23	44.856 mi
Registration #4	2012-11-05	56.381 mi
Registration #5	2013-12-04	69.386 mi
Registration #6	2014-11-25	82.224 mi
Registration #7	2015-11-06	88.786 mi
Registration #8	2016-11-30	91.730 mi
Registration #9	2017-12-11	96.330 mi
Registration #10	2018-05-22	99.377 mi
Registration #11	2018-05-22	99.377 mi
Registration #12	2018-05-22	99.377 mi
Registration #13	2018-05-22	99.377 mi
Registration #14	2018-05-22	99.377 mi
Registration #15	2018-05-22	99.377 mi
Registration #16	2018-05-22	99.377 mi
Registration #17	2018-05-22	99.377 mi
Registration #18	2018-05-22	99.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1757 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	541485